

Needs-Based Public School Capital Fund

2024-25 Grant Application

Application Deadline: September 13, 2024

Rev. 7/30/2024

NEEDS-BASED PUBLIC SCHOOL CAPITAL FUND FY2024-25 GRANT APPLICATION

PROGRAM CRITERIA

Date: _____

MAXIMUM AWARD Grant award maximums are as follows:

- Up to \$42 million for an Elementary School
- Up to \$52 million for a Middle School
- Up to \$62 million for a High School

An applicant may not apply for projects that exceed an aggregate amount greater than the maximum grant award amounts listed above in any single year.

Applications will be reviewed in the context of projected enrollment to evaluate the reasonableness of project size and scope.

REPORTING

Grant recipients are required to submit a report by April 1 of each year, with each grant funds distribution request, and upon completion of the project, detailing: the use of grant funds, progress on the project, and impact of the project on the county's school capital plan.

Grant funds will be disbursed in a series of payments based on the progress of the project. To receive a distribution, the grant recipient must submit a request for distribution, along with documentation of the expenditures for which the distribution is requested, and evidence that the matching requirement has been met. DPI will provide grant recipients with Reporting and Distribution Request forms following announcement of awards.

AGREEMENT

A county receiving Needs-Based grant funds is required to enter into an agreement with the Department of Public Instruction detailing the use of grant funds, in accordance with G.S. 115C-546.12.(a). DPI will provide grant recipients with Agreement Forms following announcement of awards. Signed Agreements are due within 60 days of award announcement.

NEEDS-BASED PUBLIC SCHOOL CAPITAL FUND FY2024-25 GRANT APPLICATION

PROGRAM CRITERIA

Date: _____

EVALUATION

Applications are evaluated on critical needs, budget detail, and the following criteria per G.S. 115C-546.10.:

| Prioritization | Definition/Calculation/Data Source |
|---------------------------------|---|
| Tier Designation | Counties designated as development tier one areas. (NC Department of Commerce, 2024 NC Development Tier Designations) |
| Ability to Generate Tax Revenue | Total revenue generated by a one-cent per \$100 valuation increase in the county property tax rate. (NC State Treasurer, Analysis of Debt of North Carolina Counties 6-30-2023) |
| Ratio of Debt to Tax Revenue | <u>Debt</u> : Sum of County Debt from [General Obligation Bonds, Installment Purchase Debt, Special Obligation Bonds, QZABs and QSCBs, Certificates of Participation] (NC State Treasurer, Analysis of Debt of North Carolina Counties 6-30-2023) <u>Revenue</u> : Sum of County Revenues from Property Taxes, Other Taxes, and Sales Tax, FY 2022-23 (NC DOR, Statistical Abstract of North Carolina Taxes 2023, Advance Edition) |
| Critical Deficiency | The extent to which a project will address critical deficiencies in adequately serving the current and future student population. |
| Facility Construction | Projects with new construction or complete renovation of existing facilities. |
| Facility Replacement | Projects that will consolidate two or more schools into one new facility. |
| Applicant Status | Counties that have not received a grant in the previous three years. |

NEEDS-BASED PUBLIC SCHOOL CAPITAL FUND FY2024-25 GRANT APPLICATION

CONTACT INFORMATION

Date: _____

SUBMIT ONE APPLICATION PER SCHOOL CAMPUS – A PROJECT MAY INCLUDE MULTIPLE BUILDINGS

County: _____

Primary Contact: _____

Title: _____

Address: _____

Phone: _____

email: _____

School Unit: _____

Primary Contact: _____

Title: _____

Address: _____

Phone: _____

email: _____

APPLICATION SUBMITTAL

Submit completed applications and supporting materials by Friday, September 13, 2024, via email to:

Nathan Maune | School Facilities Director | 984-236-2919 | SchoolPlanning-NBPSCF@dpi.nc.gov

SUBMITTAL CHECKLIST – SUBMIT ALL FILES IN PDF FORMAT

- Contact Information
- Application Form
- Project Narrative
- Budget Estimate
- Additional Documentation (as appropriate)
- Signed Assurance Page

NEEDS-BASED PUBLIC SCHOOL CAPITAL FUND FY2024-25 GRANT APPLICATION

PROJECT INFORMATION

Date: _____

Project Title:

Location:

Type of Facility:

Short Description of Proposed School Construction Project:

–

–

–

–

–

–

Describe the critical need this project addresses and the impact on student outcomes:

–

–

–

–

–

–

–

–

–

–

–

–

–

(please attach additional information as necessary)

NEEDS-BASED PUBLIC SCHOOL CAPITAL FUND FY2024-25 GRANT APPLICATION

PROJECT INFORMATION

Date: _____

Was this project identified in the 5-year plan in the 2020-21 Facility Needs Survey? ___ YES ___ NO

If not, provide explanation and attach equivalent information:

Will this project replace any existing facilities? ___ YES ___ NO

If YES, which school(s): _____

How many students will be served by this project? _____

Has Advanced Planning been done for this project? ___ YES ___ NO

Have Construction Documents been completed for this project? ___ YES ___ NO

Anticipated or Actual Bid Date: _____

Planned Start Date of Construction*: _____

Planned Completion Date of Construction: _____

*Construction must begin within 24 months of grant award under G.S. 115C-546.12.(b) .

NEEDS-BASED PUBLIC SCHOOL CAPITAL FUND FY2024-25 GRANT APPLICATION

PROJECT BUDGET

Date: _____

Total NBPSCF Grant funding requested for this project: _____

Minimum NBPSCF Grant funding for project to proceed (optional): _____

| Estimated Project Costs | Local (non-State) | NBPSCF Grant Funds | Total |
|-------------------------|-------------------|--------------------|----------|
| Planning | \$ _____ | \$ _____ | \$ _____ |
| Construction | \$ _____ | \$ _____ | \$ _____ |
| Other Costs* | \$ _____ | \$ _____ | \$ _____ |
| Total | \$ _____ | \$ _____ | \$ _____ |

*Project costs normally categorized as 'owner's direct costs' on a construction project – may include items such as site surveys, materials testing, site utilities, geotechnical reports, etc. Land acquisition costs are not eligible.

Source(s) of required Local Matching Funds:

Have any of the Local Matching Funds been expended at the time of application? ___ YES ___ NO

If YES, provide amount expended: _____

If YES, provide description of work: _____

Estimated Project Expenditures by Fiscal Year (show estimated period over which funds will be spent by Fiscal Year)

| Total Planned Expenditures | 2023-24 or earlier | 2024-25 | 2025-26 | 2026-27 or later | Total |
|---|--------------------|----------|----------|------------------|------------------|
| Local Matching Funds | \$ _____ | \$ _____ | \$ _____ | \$ _____ | \$ _____ |
| Requested NBPSCF Grant Funds* | \$ _____ | \$ _____ | \$ _____ | \$ _____ | \$ _____ |
| Total Estimated Expenditures by Fiscal Year | \$ _____ | \$ _____ | \$ _____ | \$ _____ | \$ 65,100,100.00 |

*Total requested grant funding cannot exceed maximum allowed under G.S. 115C-546.11.(c) .

NEEDS-BASED PUBLIC SCHOOL CAPITAL FUND FY2024-25 GRANT APPLICATION

ADDITIONAL DOCUMENTATION

Date: _____

Any project funded with a grant from the Needs-Based Public School Capital Fund must follow the same review process as any other LEA capital project.

- A registered Architect and/or registered Engineer shall prepare the drawings and specifications in accordance with G.S. 133-1 through 133-4.1, as applicable.
- School Planning design review is required. Design documents must be submitted at appropriate intervals during design – SD, DD, and CD. Neither the LEA nor the County shall invest any funds in construction of the project until the review process is completed.
- Transmittal of drawings and specifications to School Planning must include the form at: <https://www.dpi.nc.gov/documents/schoolplanning/project-submittal-form/download>
- Design of the project should be in compliance with DPI School Planning Guidelines: <https://www.dpi.nc.gov/districts-schools/district-operations/school-planning>
- DPI Facility Design Guidelines can be found at: <https://www.dpi.nc.gov/documents/schoolplanning/facility-design-guidelines/download>
- DPI School Science Facility Requirements can be found at: <https://www.dpi.nc.gov/documents/schoolplanning/science-facilities-planner/download>
<https://www.dpi.nc.gov/documents/schoolplanning/science-safety-checklist/download>
- For projects involving the closing of an existing school, the LEA must follow these procedures: <https://www.dpi.nc.gov/documents/schoolplanning/school-closing-procedure/download>
- For projects involving the demolition of an existing school building, the LEA must follow the closing procedure noted above and must submit a Feasibility and Cost Analysis: <https://www.dpi.nc.gov/documents/schoolplanning/costfeas-1/download>
- DPI Lottery Capital Funding FAQ can be found at: <https://www.dpi.nc.gov/documents/schoolplanning/lottery-capital-funding-faq-document/download?attachment>

NEEDS-BASED PUBLIC SCHOOL CAPITAL FUND FY2024-25 GRANT APPLICATION

ASSURANCE PAGE

Date: _____

By signing below, we assure the North Carolina Department of Public Instruction that we are officials of our respective organizations and we are authorized to submit this application on behalf of these organizations.

We certify the following:

- The information provided in this proposal is correct and complete.
- The project described in the application is within the parameters of the Needs-Based Public School Capital Fund as required in Article 38B of G.S. 115C-546, and that all of the required local funding is available and designated as a match for this project.
- All Needs-Based Public School Capital Fund grant proceeds and the required Local Matching funds will be used for the construction project described in the application.
- We will work cooperatively with the North Carolina Department of Public Instruction in monitoring and evaluating the progress of the project to meet statutory reporting requirements. We will report on project status and State and local funds expended by April 1 of each year, at the time of each distribution request, and within 90 days of project completion.
- Within 60 days of receiving a Needs-Based Public School Capital Fund grant award, we will enter into an agreement with the Department of Public Instruction detailing the use of grant funds, in accordance with G.S. 115C-546.12.(a).
- All applicable federal and state laws will be adhered to, including promotion of equal opportunity without regard to race, color, religion, gender, age, disability, political affiliation, or national origin.
- Generally accepted fiscal control and accounting procedures will be followed to ensure proper disbursement and accounting of funds from the Needs-Based Public School Capital Fund grant proceeds and required Local Matching funds.
- All Needs-Based Public School Capital Fund grant proceeds are subject to forfeiture provisions, requiring full repayment, in accordance with G.S. 115C-546.12.(c).

(Signature – Chair, County Commissioners)

(Date)

(Signature – Chair, Board of Education)

(Date)



TRANSYLVANIA COUNTY SCHOOLS

225 Rosenwald Lane, Brevard, NC 28712-3299
 828-884-6173 | www.tcsnc.org
 Dr. Lisa Fletcher, Superintendent

Board of Education
 Kimsey Jackson, Chair
 Tanya Dalton, Vice Chair
 Tawny McCoy
 Bryan O'Neill
 Chris Wiener

Continuation of Short Description of Proposed Construction Project

This project will improve student safety by consolidating two deteriorating buildings. It will also allow for more academic opportunities for our students by remodeling our CTE, Exceptional Children, and Performing Arts wing, which will build corridors to enclose the campus. If funded, this grant will replace the current cafeteria and auxiliary gym that houses our MCJROTC program at Brevard High School. There are 34 exterior doors on Brevard High School's Campus between nine building wings. Each wing houses a specific academic area.

The construction project will build a 59,116-square-foot cafeteria and gym facility. The current square footage of the cafeteria is only 3,900, which is smaller than what DPI recommends. These current facilities were due to be replaced by a bond passed in 2018. Due to rising construction costs, COVID, and many facility needs across all campuses, there is no longer funding to replace these two buildings or complete the necessary repairs. This new facility will enable Transylvania County Schools to eliminate two outdated buildings that, according to an Engineer inspection from April 2024, have a life of 5 years. The five-year life is after current repairs to the beams. The proposed construction of a consolidated gym and cafeteria would allow for more seating and updated athletic facilities to accommodate our MCJROTC program, which currently serves all three of our high schools at this location.

The safety portion is threefold: creating a single-point entrance, replacing the deteriorating buildings, which is related to the safety of the students from structural failure, and remodeling the CTE and EC wing, which will address safety from threats from outside of the building. Having 9 distinct and separate buildings on campus creates a significant campus safety challenge, including unsecured access to classrooms, various entry points to the facility, and moving vehicles around the building. Students traveling outside between buildings on campus creates a significant campus safety challenge. Students travel outside between buildings during every class change, leaving as many as 34 exterior doors unsecured. This safety concern and a porous perimeter between buildings present a safety risk that can allow unauthorized access to campus buildings and high visibility and exposure of students to the surrounding public. The proposed construction project would restrict access and secure the campus and grounds. This project is critical in assisting in efforts to keep all students in a safe environment. Remodeling the CTE and Exceptional Children's wing will not only remove the need for students to travel outside between the buildings but also provide a critical investment in enhancing student performance and success in the workforce. Modernized facilities can provide students access to the latest technology and tools used in today's industries, bridging the gap between education and real-world applications. Current facilities are considerably smaller than the state recommendation for square footage for most of our program areas. We have also used all usable power sources and are due to a considerable

upgrade to our circuit boards and capacity within the CTE building. We cannot bring in new technology as we can not provide sufficient power to operate CNC tables and modern equipment. We do not have a spare circuit anywhere in the building. Up-to-date classrooms foster an engaging and hands-on learning environment, allowing students to develop practical skills directly transferable to their future careers.

Additionally, well-designed spaces can improve collaboration, creativity, and critical thinking—essential skills needed in any profession. By aligning the educational environment with current industry standards, students are better prepared to meet the demands of the workforce, resulting in higher employability and greater long-term success. Also, it would allow for ADA-accessible classrooms with appropriate desks and tables for students who use wheelchairs. As students often require hospital beds to attend school, proper room size would allow for more individualized and inclusive learning.

In addition, remodeling the Exceptional Children’s Wing will enhance student outcomes by creating more accessible, supportive, and adaptable learning environments tailored to their unique needs. Updated spaces can better accommodate sensory, mobility, and communication requirements, promoting engagement, comfort, and overall academic success.

Remodeling the art classroom and auditorium will elevate student outcomes by providing state-of-the-art spaces that inspire creativity, collaboration, and expression. Updated facilities will enhance the learning experience by offering students the proper tools and environments to fully explore and develop their artistic talents, leading to greater skill development and confidence in their craft.

Transylvania County and Transylvania County Schools have invested significant local financial resources and time to begin much-needed repairs throughout the district. In February 2023, the Transylvania County Commissioners and Transylvania County School Board jointly signed an agreement to conduct a facility needs assessment. The total cost of the facilities assessment showed that the district needs are over 94 million based on 2024 costs. The assessment report also identified increasing yearly maintenance costs because of aging buildings and utility infrastructure, a growing list of costly deferred maintenance items, and structural concerns in some buildings. Receiving the NBPSCF will allow for all needed renovations at Brevard High School to be met, and then the 68 million dollar bond can meet the needs of the other schools throughout the district.

The total repairs identified by Axias for Brevard High School were \$29,896,843. The total estimated capital repairs for all 9 school buildings in Transylvania County is \$94,338,781. The total bond funds available for the repairs is \$68,000,000. If we receive the 62 million dollar grant, we can complete all the identified repairs to Brevard High School. We can also build a new consolidated facility for the cafeteria and gym, which is currently recommended for inspection of life every two years. With this grant, the CTE wing, Exceptional Children, Science, and Arts wing can all be renovated. This grant funding will mean the total bond fund will be available for the other school buildings that have identified needed repairs, including a planned renovation to Rosman High and Rosman Middle Schools.

A replacement gym and cafeteria will provide the following:

- Square footage of the program in accordance with NCDPI Facility Space Guidelines.

TCS
Attachment A

- Replaces two dilapidated structures, reducing the chance of a structural breakdown and improving campus security as a whole.
- Reducing the amount of external doors and entrance points by consolidating functions into a single building enhances campus security and lowers unwanted access.
- In order to better support athletic events and the MCJROTC program, the district's three high schools as well as all eighth students will benefit from the larger, more contemporary gym it offers.
- The cafeteria will be upgraded from its existing unsatisfactory 3,900 square feet to a larger space that complies with state regulations.

Remodel of our CTE, Exceptional Children, and Arts classrooms will provide the following:

- A single-point entry of the building
- Assure our students are not affected by outside weather conditions as they move throughout the campus.
- Provide a safe environment as our students move from class to class.
- Supports the implementation of state-of-the-art technology and tools in the CTE wing, enhancing hands-on learning and better preparing students for the workforce
- Provides ADA-accessible classrooms and appropriate furnishings to support students with disabilities, promoting an inclusive learning environment.
- Upgrades to the Exceptional Children's Wing to create adaptable and supportive spaces tailored to diverse student needs, improving engagement and academic success.

The entire construction project will provide the following long-term financial benefits:

- The new facility helps address immediate facility needs and safety concerns, allowing remaining bond funds to be allocated for other district-wide repairs and renovations.
- Ensures that Brevard High School's facilities remain functional and up-to-date, potentially extending their usable life and reducing future maintenance costs.

FACILITY CONDITION ASSESSMENT SUMMARY REPORT



Prepared For:

Transylvania County Board of Commissioners
101 South Broad Street
Brevard, NC 28712

Prepared By:

Axias
Project No. GA23-017
March 1, 2024

Axias
BUILDING VALUE

TABLE OF CONTENTS

| SECTION | PAGE |
|---|-------------|
| EXECUTIVE SUMMARY..... | 2 |
| FINANCIAL SUMMARY..... | 2 |
| EXPENDITURES BY YEAR..... | 3 |
| EXPENDITURES BY CATEGORY..... | 3 |
| EXPENDITURES BY PRIORITY..... | 5 |
| EXPENDITURES BY SYSTEM..... | 6 |
| EXPENDITURES BY RISK PRIORITIZATION | 7 |
| FACILITY CONDITION INDEX COMPARISON | 8 |
| CONCLUSIONS AND NEXT STEPS..... | 9 |
| FACILITY CONDITION ASSESSMENT METHODOLOGY | 11 |
| OPINION OF COST | 11 |
| USEFUL LIFE DEVELOPMENT | 12 |
| RISK PRIORITIZATION METHODOLOGY | 12 |

APPENDICES

A Step One Investment Plan Projects



EXECUTIVE SUMMARY

To stabilize and preserve the Transylvania County school facilities, significant investments are required over the next ten years. This report provides a summary of the financial requirements and key issues identified for the facilities included within the assessment. It should be noted that the assessment did not address improvement items related to educational adequacy, functionality, space utilization, student capacity, etc. and primarily focused on the core infrastructure supporting each existing school.

Overall, the school facilities are in Fair condition when assessing them from a systems and structural condition standpoint. Capital investments over the years have primarily focused on life cycle replacement of mechanical equipment and life extension measures to roofing systems along with some select roof replacements. Interior finishes within the schools typically date to the last renovation or addition and appeared to be dated but remain functional. The primary purpose of the condition assessment was to develop a strategic long range capital plan that the County could utilize to properly budget and plan for addressing the deferred maintenance backlog and future capital renewal requirements

A reactionary approach of repairing or replacing upon failure is one that comes with inherent risk. To fully comprehend the magnitude of these risks, one must weigh the cost of the system or component renewal versus the costs incurred at the time of a system failure along with potential collateral costs resulting from the failure. Reactionary spending carries a higher premium of sometimes up to 75% or more than typical proactive capital renewal projects.

A strategic proactive approach must be taken to help mitigate the inherent risks associated with aged systems and components. To accomplish this, a structured multiyear capital investment plan must be implemented. A strategic capital investment plan focusing on reducing the deferred maintenance backlog along with planning for future capital renewal items will help ensure that the operations and overall mission of Transylvania County Schools is not impacted.

FINANCIAL SUMMARY


The following section provides a summary of the capital investment requirements over the ten-year study period for the school facilities included. All costs are provided in 2024 dollars and exclude design fees, insurance, permits, CM fees, etc., which can range from an additional 30-40%.

Total Expenditures by Buildings

| School Facility | Ten Year Expenditures |
|--------------------------|-----------------------|
| Brevard Elementary | \$11,487,210 |
| Brevard Middle School | \$11,466,210 |
| Brevard High School | \$29,896,843 |
| Davidson River School | \$2,173,724 |
| Pisgah Forest Elementary | \$7,623,303 |
| Rosman Elementary | \$6,907,940 |
| Rosman Middle & High | \$19,041,791 |
| TC Henderson Elementary | \$4,349,205 |
| Plant Operations | \$543,906 |
| Morris Education Center | \$848,750 |
| TOTAL | \$94,338,781 |

EXPENDITURES BY YEAR

Total Expenditures by Year





EXPENDITURES BY CATEGORY

A classification category has been assigned for each recommendation which helps group expenditures based on why it should be completed. We have classified each recommendation by one of the five classifications:

| Category | Definition | Description |
|----------|-----------------------|--|
| SM | Scheduled Maintenance | Scheduled maintenance is major maintenance that is typically required to maintain effective operation of an asset and/or prolong the lifecycle. This does not include items related to preventative maintenance activities and typically have a requirement total of over \$5,000. |
| CR | Capital Renewal | Capital Renewal projects correct unacceptable conditions caused by aged building components which will exceed their useful life cycle within the next ten years. These items generally function as originally intended. If execution of Capital Renewal projects is deferred for an inordinate amount of time, conditions may deteriorate, and the projects may be re-categorized as Deferred Maintenance. |

| Category | Definition | Description |
|----------|----------------------|--|
| DM | Deferred Maintenance | Deferred Maintenance is maintenance or repair that is past due. This work will return a component or system to an acceptable condition, prevent physical depreciation or loss in the value of a building, minimize or correct wear, and maintain the maximum reliability and current useful life of the facility or component. |
| EN | Energy | When the repair works, or replacement of equipment, or systems are recommended to improve energy and sustainability performance. |
| CI | Capital Improvement | When a recommendation to install or upgrade a system component improves or enhances the performance or functionality of the facility. |

Total Expenditures by Category
Total Expenditures by Category by Year




Most of the expenditures identified are considered to be Capital Renewal; however, the County will need to address the combined \$15,470,688 of Deferred Maintenance in a timely manner or future Capital Renewal will become Deferred Maintenance. The greatest Deferred Maintenance expenditures are attributable to roof replacements which total approximately \$7,500,000. A strategic approach to addressing the deferred maintenance backlog will need to be developed. The backlog will continue to increase annually if not addressed.

EXPENDITURES BY PRIORITY


To provide ease of project prioritization within the expenditure forecast, we have prioritized each expenditure by criticality. These priorities are listed and described in the table below.

| Priority | Definition | Description |
|----------|---------------------------------|--|
| I | Currently Critical | Conditions in this category require immediate action to either correct a cited safety hazard, stop accelerated deterioration, or return a facility/system to operation |
| II | Potentially Critical | Conditions in this category, if not corrected expeditiously, will become critical within a year. |
| III | Necessary / Not yet Critical | Conditions in this category require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further. |
| IV | Recommended | Conditions in this category include items that represent a sensible improvement to existing conditions. These are not required for the most basic function of the facility. |
| V | Appearance | Conditions in this category include finishes that have deteriorated and are required to maintain the required aesthetic standards. |
| VI | Does Not Meet Codes / Standards | Conditions in this category include items that do not conform to existing codes which maybe "grandfathered" in their condition. |

Expenditures by Named Priority




Expenditures by Named Priority by Year



EXPENDITURES BY SYSTEM

Each recommendation and expenditure are also grouped by system or facility element. This will allow the County to identify projects that could potentially be grouped into one project.



Expenditures by System



Most of the expenditures identified are attributable to renewal of the Interior finishes. Allowances for renewal of the interior finishes have been included at each school and generally exclude reconfiguration of space and/or improvements and only focus on renewing finishes in kind. Since the finishes are functional, the timing of these expenditures is not as critical as renewal of building systems or components and could potentially allow for flexibility for alternatives, such as improvements or enhancements not considered by this study. The second and third greatest needs relate to renewal of mechanical systems and roof replacements at each of the schools.

EXPENDITURES BY RISK PRIORITIZATION

To allow the County to weigh the risks of capital investment versus capital deferment, we have assigned each recommendation a risk number. The risk prioritization methodology is detailed in the Facility Condition Assessment Methodology section of this report. The table below shows the identified expenditures by risk category. A complete risk assignment for each recommended expenditure is included in each individual report provided to the County.



FACILITY CONDITION INDEX COMPARISON

The Facility Condition Index (FCI) provides a relative measure for comparing one facility (or group of facilities) to another. This index is a calculation derived by dividing the total project cost for the first year of the study period by the total current replacement value of the building.

In addition, the Facility Condition Needs Index (FCNI) is similar to the FCI but helps assist in comparing the expenditure needs of one facility versus a group of facilities over a period of time. The FCNI also shows the cumulative effects if the deferred maintenance and capital renewal expenditures are not addressed in a timely manner. This index is a calculation, derived by dividing the total recommended expenditures over the entire 10-year study period by the total CRV of the building. The index is intended to show the current and future conditions of the building if no capital investment is made over the next 10 years.

Facility Condition Index & Facility Condition Needs Index

| Facility | Current FCI | 10-Year FCNI | Current FCI | 10-Year FCNI |
|--------------------------|-------------|--------------|---------------|--------------|
| Brevard Elementary | 0.10 | 0.47 | Fair | Poor |
| Brevard Middle School | 0.10 | 0.42 | Below Average | Poor |
| Brevard High School | 0.16 | 0.64 | Below Average | Renew |
| Davidson River School | 0.01 | 0.33 | Excellent | Poor |
| Pisgah Forest Elementary | 0.01 | 0.38 | Excellent | Poor |
| Rosman Elementary | 0.06 | 0.45 | Fair | Poor |
| Rosman Middle & High | 0.10 | 0.42 | Below Average | Poor |
| TC Henderson Elementary | 0.09 | 0.54 | Fair | Renew |
| Plant Operations | 0.04 | 0.27 | Good | Poor |
| Morris Education Center | 0.02 | 0.21 | Good | Poor |

FCI / FCNI Condition Ranges

| Individual FCI Range | Condition Description |
|----------------------|---|
| 0.00 - 0.02 | Excellent condition, major systems and components have recently been installed or upgraded. |
| 0.02 - 0.05 | Good condition, renovations have occurred on schedule |
| 0.05 - 0.10 | Fair condition, in need of normal renovation |
| 0.10 - 0.20 | Below average condition, major renovation required |
| 0.2 - 0.5 | Poor Condition, major renovation indicated |
| 0.5 and above | Renew, complete facility renovation required, or potential replacement indicated |

The current FCIs range significantly from Excellent to Below Average, typically reflecting whether a building has been subject to a substantial system replacement or refurbishment. Overall, the County's school facilities are in Fair condition when averaging the current condition indexes. The FCI does not consider the capacity or programmatic needs of the facility and typically only is utilized to understand the current condition of the major systems and components regardless of age of interior finishes. Future programmatic requirements, when identified, should be considered when evaluating a facility FCI to determine if the cost of the programmatic requirements and required expenditures is financially prudent, or does it make more sense to construct a new facility.

The table above further shows that if significant capital investment in the facilities is not made, the range of ratings changes from Good through to Renew by year ten. Anything considered to be in fair condition or worse will likely require significant investment / renovation.

CONCLUSIONS AND NEXT STEPS

As a result of the initial condition assessments, additional follow-up studies were identified and completed. This included indoor air quality testing, additional structural evaluations at the Brevard High Old Gymnasium, and a physical security assessment of all the schools. The assessments provided additional information that was vital in developing the recommendations. The initial facility assessments, along with the follow up assessments, are the first steps of the process in understanding the existing conditions of the schools so that a strategic plan can be developed to address the current deferred maintenance backlog and plan for future capital renewal needs. It should be noted that these expenditures are above and beyond typical operating and maintenance expenditures, and do not address needs related to educational adequacy, learning environments and technology, capacity, etc. and only focus on stabilization and preservation of the existing school facilities.

The results of the assessments were then presented to the Capital Work Group. After several working sessions, the group identified a listing of top priority projects which should be completed in the next five to seven years. The listing of projects is provided in Appendix A. These projects address current deferred maintenance as well as required capital renewal to stabilize and preserve the systems and major components of each school.

The table below provides a financial summary of the identified capital expenditures at each school as a result of the Capital Work Group.

Step One Investment Plan

| Facility | Expenditures |
|--------------------------|----------------------|
| Brevard Elementary | \$4,687,788 |
| Brevard Middle School | \$4,339,430 |
| Brevard High School | \$17,823,962 |
| Davidson River School | \$717,084 |
| Pisgah Forest Elementary | \$3,025,833 |
| Rosman Elementary | \$4,452,310 |
| Rosman Middle & High | \$10,336,991 |
| TC Henderson Elementary | \$1,861,080 |
| Plant Operations | \$401,156 |
| Morris Education Center | \$178,240 |
| TOTAL | \$47,823,874* |

***Costs exclude design fees, insurance, permits, CM fees, etc.**

Now that the initial assessments are complete and required expenditures have been identified, additional project planning must be completed to determine how best to package and execute the projects. To do so, it is necessary to conduct a series of charrettes to review the recommended projects at each school and identify projects that can be grouped together and/or may impact other work that needs to be completed. Each school should not be viewed independently but opportunities to group like projects across the portfolio should also be identified. For instance, grouping similar work packages for exterior facades or roofs across the portfolio can often achieve economy of scale cost savings. Once this is complete, work packages can then be developed and executed with a complete project budget.

In addition to addressing the identified expenditures, the County and school system will also need to begin planning on how to fund future capital renewal once existing funds have been expended. Current capital funding levels should be evaluated and adjusted now to assure reserves are sufficient to address capital requirements in a timely manner in conjunction with a joint multiyear capital renewal plan. This approach will allow the County and school system to implement a proactive capital program.

FACILITY CONDITION ASSESSMENT METHODOLOGY

The objective of this report is to produce a holistic facilities assessment and capital planning process that will result in a strong and well-developed plan to support strategic capital investment and to identify and reduce risk. In short, the objective is to assess the condition of all included buildings and site systems to develop a prioritized forecast of anticipated capital expenditures over the 10-year study period between 2024 and 2033. This will inform the long-term investment plan for the facilities by developing an array of projects that can be entered into a planning model from which sound management decisions can be made to best utilize funding resources. Specific objectives of this study are listed below:

- Identification and documentation of the present condition and risks of each facility
- Recommendation of corrections for all deficiencies
- Provision of cost estimates for such corrections
- Forecasting of future facility renewal costs based on documented methodology of the facilities and equipment in the facilities
- Obtaining a Facilities Condition Index (FCI) and Facility Condition Needs Index (FCNI) to illustrate the relative condition of the subject facility

The primary purpose of the facilities condition assessment was to identify visually apparent deficiencies in the building systems and site. The evaluation included site visits to observe the building and site systems, interviewing building management and maintenance personnel, reviewing available maintenance systems, design, and construction documents, and plans where provided. Axias was provided with limited existing documentation regarding as-built and/or design drawings.

OPINION OF COST

Opinions of cost presented within this report are based upon experience with past costs for similar projects, consulting with local specialty contractors, client provided information, city cost indexes, construction costs developed by construction resources such as RS Means and assumptions regarding future economic conditions. Actual cost estimates are determined by many factors including but not limited to, choice and availability of materials, choice and availability of qualified contractors, regional climate zone, quality of existing materials, site compatibility, and access to the subject property and buildings. If any cost items listed are considered critical in decision making regarding this property, we recommend that contractor or supplier quotations be obtained for those items before making final decisions about this property. Opinions of cost also typically exclude design fees, contractor markups, insurances, permits, etc.

Costs for work that we consider as normal maintenance for a facility, including items which can be completed for less than \$4,000, work normally performed by the on-site maintenance staff, or work which is routinely contracted, may not be included in our cost evaluation but may be listed as maintenance/operational items.

The opinions of cost provided should be utilized for budgetary purposes and may fluctuate based on the final determined scope of work, contract delivery method, project schedule, economy of scale, phasing, etc. In addition, the opinions of cost do not include mark ups for design, engineering, contractor overhead and profit, general conditions, permitting and licensing, insurance, and other typical project mark ups.

USEFUL LIFE DEVELOPMENT

A fundamental part of any capital planning process is the development of the Estimated Useful Life (EUL) and Remaining Useful Life (RUL) for each piece of equipment. EUL considers the life of a system or component of that system while RUL considers the remaining life of that system.

We developed our EUL and RUL based upon the determined condition, our professional experience, and the criticality of the system. Additional factors can also impact the RUL of a system, such as the level of maintenance that is conducted. The EUL is typically derived from industry standard publications, while the RUL is typically derived by location specific factors.

RISK PRIORITIZATION METHODOLOGY

To balance containment of capital investment with probability and consequence of failure, we have assigned each recommendation with a risk priority number. Risk priority numbers have been calculated based upon assignment of risk resulting from criticality, impact of failure, condition, and failure probability. Numerical scores from each element are added to provide an end risk priority number; the lower the number, the greater the risk if the recommendation is not completed. The risk priority numbers are based on a per year basis. By providing each expenditure recommendation with a risk priority number, it helps further prioritize expenditures so that funding can be directed to expenditures that could potentially have the most impact if not addressed in a timely manner. The sum of the numbers assigned to each category creates a total risk number, which equates to a risk category based upon its numerical range. Refer to the table below for details on each of the categories:

| SCORE | IMPACT OF FAILURE | CONDITION/ OBSERVED DEFICIENCIES | FAILURE PROBABILITY |
|-------|--|--|----------------------------------|
| 5 | No impact on operations | VERY GOOD | No chance of failure |
| 4 | Intervention required to maintain operations | GOOD | Minimal probability of failure |
| 3 | Scaled back operations and interruption of activities | FAIR | Slight probability of failure |
| 2 | Interruption of facility's primary use and critical operations severely affected | POOR | Increased probability of failure |
| 1 | Major system/facility shutdowns | VERY POOR | In state of failure |

Appendix A

Step One Investment Plan Projects



Transylvania County Schools
Focus Projects
2024-2031

| Project Year | Building | Recommendation | System | Priority Category | Deficiency Category | Risk Category | Anticipated Cost |
|--------------|--------------------|---|--------------------|-------------------|---------------------|---------------|---------------------|
| 2024 | Brevard Elementary | Repaint all exterior painted elements including profiled metal sheeting, lintels, doors and handrails where provided - Cycle 1. | Exterior Elements | III | DM | Medium | \$30,870. |
| 2024 | Brevard Elementary | Replace exterior sealants. | Exterior Elements | III | DM | Medium | \$23,000. |
| 2024 | Brevard Elementary | Upgrade fire alarm control panel and as needed devices. | Fire & Life Safety | III | CR | Medium | \$20,000. |
| 2024 | Brevard Elementary | Provide additional exit signage and egress lighting. | Fire & Life Safety | VI | DM | Medium | \$16,500. |
| 2024 | Brevard Elementary | Complete life safety and code evaluation. | Fire & Life Safety | III | CI | Medium | \$10,000. |
| 2024 | Brevard Elementary | Replace stained and/or damaged ceiling tiles. | Interiors | III | DM | Low | \$16,000. |
| 2024 | Brevard Elementary | Install new BMS system throughout building. | Mechanical | III | DM | Medium | \$204,920. |
| 2024 | Brevard Elementary | Replace natural gas fired boiler along with the pumps, valves, and accessories.. | Mechanical | II | CR | Medium | \$108,350. |
| 2024 | Brevard Elementary | Replace Reznor MUA unit. | Mechanical | III | CR | High | \$40,000. |
| 2024 | Brevard Elementary | Replace ICP R22 ICP complete cooling system. | Mechanical | III | CR | High | \$18,000. |
| 2024 | Brevard Elementary | Replace built-up roof with TPO system. | Roofing Systems | II | DM | High | \$1,712,500. |
| 2024 | Brevard Elementary | Replace profiled metal covering along walkways. | Roofing Systems | III | DM | Low | \$126,000. |
| 2024 | Brevard Elementary | Repair sealants where disconnected and deteriorated. | Roofing Systems | III | DM | Medium | \$8,500. |
| 2024 | Brevard Elementary | Full-depth replacement of damaged localized sections of asphalt pavement. | Site Systems | III | DM | High | \$59,738. |
| 2024 | Brevard Elementary | Crack fill, seal coat and restripe asphalt surfaces - Cycle 1. | Site Systems | III | SM | Low | \$26,550. |
| 2024 | Brevard Elementary | Replace localized sections of concrete sidewalks. | Site Systems | III | DM | Low | \$7,800. |
| 2025 | Brevard Elementary | Allowance to improve school security systems and school safety. | Electrical | II | CI | High | \$283,400. |
| 2025 | Brevard Elementary | Construct vestibules per Physical Security Assessment. | Interiors | II | CI | High | \$174,400. |
| 2025 | Brevard Elementary | Remove underground storage tank and install new above ground code/regulation compliant storage tank. | Plumbing | II | CR | High | \$175,000. |
| 2025 | Brevard Elementary | Install additional site fencing. | Site Systems | III | CI | Medium | \$36,000. |
| 2026 | Brevard Elementary | Replace 2001 Burnham Boiler along with the pumps, valves, and accessories.. | Mechanical | III | CR | Medium | \$304,640. |
| 2028 | Brevard Elementary | Replace original GE electrical equipment. | Electrical | III | CR | High | \$523,200. |
| 2028 | Brevard Elementary | Replace air handling units throughout the building. | Mechanical | III | CR | Medium | \$315,000. |
| 2030 | Brevard Elementary | Replace AO Smith commercial water heaters. | Plumbing | IV | CR | Low | \$90,000. |
| 2030 | Brevard Elementary | Replace playground equipment. | Site Systems | IV | CR | Low | \$300,000. |
| 2031 | Brevard Elementary | Repaint all exterior painted elements including profiled metal sheeting, lintels, doors and handrails where provided - Cycle 2. | Exterior Elements | IV | SM | Medium | \$30,870. |
| 2031 | Brevard Elementary | Crack fill, seal coat and restripe asphalt surfaces - Cycle 2. | Site Systems | III | SM | Low | \$26,550. |
| | | | | | | | \$4,687,788. |

Costs exclude design fees, permits, insurance, CM fees, etc.

Transylvania County Schools
Focus Projects
2024-2031

| Project Year | Building | Recommendation | System | Priority Category | Deficiency Category | Risk Category | Anticipated Cost |
|--------------|---------------------|---|--------------------|-------------------|---------------------|---------------|------------------|
| 2024 | Brevard High School | Install floor drain system in the main boiler room. | Electrical | III | DM | Medium | \$10,000. |
| 2024 | Brevard High School | Complete masonry restoration and repairs at the Old Gym. | Exterior Elements | III | DM | High | \$356,250. |
| 2024 | Brevard High School | Replace windows at the English Wing and Office Area. | Exterior Elements | III | DM | High | \$264,000. |
| 2024 | Brevard High School | Complete exterior restoration project to the building exteriors. Cycle One. | Exterior Elements | III | DM | High | \$200,000. |
| 2024 | Brevard High School | Replace high level windows at the Old Gym and Old Gym Locker Rooms. | Exterior Elements | III | DM | High | \$168,000. |
| 2024 | Brevard High School | Remove failed sealant joints and replace. | Exterior Elements | II | DM | High | \$88,000. |
| 2024 | Brevard High School | Repoint brickwork on gable elevation at junction with lower roof and replace metal flashing. Repoint brickwork on southern elevation where cracked. | Exterior Elements | III | DM | High | \$80,750. |
| 2024 | Brevard High School | Replace windows at the Media Center/Guidance Wing. | Exterior Elements | III | DM | High | \$55,000. |
| 2024 | Brevard High School | Surface prep glulam beams and repaint the exposed exterior beams with a suitable exterior wood paint. | Exterior Elements | II | DM | High | \$54,000. |
| 2024 | Brevard High School | Replace windows at the Home Economics Wing. | Exterior Elements | III | DM | High | \$33,000. |
| 2024 | Brevard High School | Replace high level window panes at each side of the gable wall. | Exterior Elements | III | DM | Medium | \$31,500. |
| 2024 | Brevard High School | Surface prep glulam beams and repaint the exposed exterior beams with a suitable exterior wood paint. | Exterior Elements | III | DM | High | \$18,000. |
| 2024 | Brevard High School | Complete life safety and code evaluation. | Fire & Life Safety | III | CI | Medium | \$15,000. |
| 2024 | Brevard High School | Construct pre-engineered metal building for wrestling teams. | Interiors | II | CI | High | \$825,000. |
| 2024 | Brevard High School | Replace stained and/or damaged ceiling tiles. | Interiors | III | DM | Low | \$20,000. |
| 2024 | Brevard High School | Remove damaged plaster, install new plaster, and repaint. | Interiors | III | DM | Low | \$8,750. |
| 2024 | Brevard High School | Allowance for replacement of corroded piping, valves, and damaged insulation. | Mechanical | III | DM | Medium | \$132,000. |
| 2024 | Brevard High School | Replace 10-ton split system units at the Media Center and New Gym. | Mechanical | III | DM | High | \$84,000. |
| 2024 | Brevard High School | Replace roof to Old Gym with new TPO membrane, including as needed roof decking replacements. | Roofing Systems | II | DM | High | \$540,000. |
| 2024 | Brevard High School | Replace standing seam metal roof at the Math Wing. | Roofing Systems | II | DM | High | \$494,400. |
| 2024 | Brevard High School | Replace standing seam metal roof at Media Center/Guidance wing. | Roofing Systems | II | DM | High | \$451,500. |
| 2024 | Brevard High School | Replace standing seam metal roof coverings. | Roofing Systems | II | DM | High | \$310,000. |
| 2024 | Brevard High School | Replace the metal roof at the Boiler Room. | Roofing Systems | II | DM | High | \$72,000. |
| 2024 | Brevard High School | Replace roof at EC wing with TPO membrane. | Roofing Systems | II | DM | High | \$69,300. |
| 2024 | Brevard High School | Replace roof at Science Building Foyer with TPO membrane. | Roofing Systems | II | DM | High | \$9,900. |
| 2024 | Brevard High School | Mill and overlay asphalt at the visitor gym/stadium parking. | Site Systems | III | DM | Medium | \$85,125. |
| 2024 | Brevard High School | Install handrails at aisles and metal ramps. | Site Systems | II | DM | High | \$79,200. |
| 2024 | Brevard High School | Repair spalled pre-cast concrete. Clean and coat metal connector plates. | Site Systems | III | DM | Medium | \$60,000. |

Costs exclude design fees, permits, insurance, CM fees, etc.

Transylvania County Schools
Focus Projects
2024-2031

| Project Year | Building | Recommendation | System | Priority Category | Deficiency Category | Risk Category | Anticipated Cost |
|--------------|---------------------|---|--------------------|-------------------|---------------------|---------------|------------------|
| 2024 | Brevard High School | Provide waterproofing membrane at concrete masonry unit walls of the dugouts. | Site Systems | III | DM | Medium | \$36,000. |
| 2024 | Brevard High School | Repair clear chain link fencing and repair damaged sections at recreation field and stadium parking lot. | Site Systems | III | DM | Medium | \$17,500. |
| 2024 | Brevard High School | Excavate externally and replace failed waterproofing membrane. Remove damaged plaster internally and repaint. | Structural Systems | II | DM | Medium | \$112,500. |
| 2025 | Brevard High School | Allowance to improve school security systems and school safety. | Electrical | II | CI | High | \$588,380. |
| 2025 | Brevard High School | Construct vestibules per Physical Security Assessment. | Interiors | II | CI | High | \$220,642. |
| 2025 | Brevard High School | Application of auxiliary systems (4 areas) to control humidity should be engineered by a qualified mechanical engineer. | Mechanical | III | CR | Medium | \$3,000,000. |
| 2025 | Brevard High School | Replace air handling units and unit ventilators. | Mechanical | III | DM | High | \$2,647,710. |
| 2025 | Brevard High School | Upgrade building management system (BMS) and main controllers. | Mechanical | III | CR | Medium | \$330,750. |
| 2025 | Brevard High School | Replace standing seam metal roof at the Auditorium and Auditorium Storage/Hall. | Roofing Systems | III | CR | Medium | \$580,000. |
| 2025 | Brevard High School | Replace EPDM and standing seam metal roofs at the Band/Drama Rooms | Roofing Systems | III | CR | Medium | \$180,000. |
| 2025 | Brevard High School | Replace softball field lighting. | Site Systems | III | CR | Medium | \$120,000. |
| 2025 | Brevard High School | Mill and overlay asphalt at the parking lot across the street. | Site Systems | III | DM | Medium | \$93,000. |
| 2025 | Brevard High School | Mill and overlay asphalt to the access road areas and staff/visitor parking lot. | Site Systems | III | CR | Low | \$75,000. |
| 2026 | Brevard High School | Upgrade antiquated electrical panels throughout the building. | Electrical | III | CR | High | \$660,000. |
| 2026 | Brevard High School | Complete exterior restoration project to the building exteriors. Cycle Two. | Exterior Elements | III | SM | High | \$200,000. |
| 2026 | Brevard High School | Overhaul Boiler #1, #2, & #5 in the vocational wing | Mechanical | III | SM | Medium | \$252,665. |
| 2026 | Brevard High School | Remove underground storage tanks and install new above ground code/regulation compliant storage tank. | Plumbing | III | CR | High | \$275,000. |
| 2026 | Brevard High School | Replace the roof at the Vocational Wing and CTE Welding/Masonry | Roofing Systems | III | CR | Medium | \$721,600. |
| 2026 | Brevard High School | Mill and overlay asphalt at the visitor gym/stadium parking. | Site Systems | III | CR | Low | \$84,750. |
| 2027 | Brevard High School | Replace heating hot water pump packages and valve assemblies. | Mechanical | III | CR | Medium | \$120,000. |
| 2027 | Brevard High School | Replace chilled water pump packages and valve assemblies. | Mechanical | III | CR | Medium | \$90,000. |
| 2027 | Brevard High School | Crack fil, seal coat, and restripe the student/school bus parking lot. | Site Systems | III | SM | Low | \$18,500. |
| 2028 | Brevard High School | Complete exterior restoration project to the building exteriors. Cycle Three. | Exterior Elements | III | SM | Medium | \$200,000. |
| 2028 | Brevard High School | Repaint soffits and supporting structure of metal breezeways across the site. | Exterior Elements | III | SM | Low | \$97,500. |
| 2028 | Brevard High School | Replace roof mounted chillers serving the Vocational wing. | Mechanical | III | CR | Medium | \$315,000. |
| 2028 | Brevard High School | Replace pad mounted Chiller #2 at the north wing. | Mechanical | III | CR | Medium | \$294,000. |
| 2028 | Brevard High School | Replace Boiler #1 and #2 along with associated controls, valves, etc. | Mechanical | III | CR | Medium | \$127,390. |

Costs exclude design fees, permits, insurance, CM fees, etc.

Transylvania County Schools
 Focus Projects
 2024-2031

| Project Year | Building | Recommendation | System | Priority Category | Deficiency Category | Risk Category | Anticipated Cost |
|--------------|---------------------|--|--------------------|-------------------|---------------------|---------------|----------------------|
| 2030 | Brevard High School | Complete exterior restoration project to the building exteriors. Cycle Four. | Exterior Elements | IV | SM | Medium | \$200,000. |
| 2030 | Brevard High School | Replace PVI natural gas fired water heaters. | Plumbing | IV | CR | Medium | \$135,000. |
| 2030 | Brevard High School | Replace standing seam metal roof at the English Wing and Office Area. | Roofing Systems | IV | CR | Low | \$707,400. |
| 2031 | Brevard High School | Replace fire alarm control panel and as needed devices. | Fire & Life Safety | IV | CR | Low | \$75,000. |
| 2031 | Brevard High School | Replace the standing seam metal roof at the Football Field House. | Roofing Systems | IV | CR | Low | \$332,000. |
| 2031 | Brevard High School | Replace standing seam metal roof at the Home Economics Wing | Roofing Systems | IV | CR | Low | \$302,000. |
| | | | | | | | \$17,823,962. |

Costs exclude design fees, permits, insurance, CM fees, etc.

Transylvania County Schools
Focus Projects
2024-2031

| Project Year | Building | Recommendation | System | Priority Category | Deficiency Category | Risk Category | Anticipated Cost |
|--------------|-----------------------|---|--------------------|-------------------|---------------------|---------------|---------------------|
| 2024 | Brevard Middle School | Create an ADA-compliant ramp from the lower parking lot/playground level up to the main school level. | Accessibility | VI | CI | Medium | \$50,000. |
| 2024 | Brevard Middle School | Break out raised concrete at canopy, separating direct route from parking spaces to entrance, to provide level access route to main entrance. | Accessibility | VI | CI | Medium | \$7,500. |
| 2024 | Brevard Middle School | Upgrade vintage GE electrical components throughout the school and replace 30-Kw emergency power generator. | Electrical | III | DM | High | \$750,880. |
| 2024 | Brevard Middle School | Replace fogged IGU's where necessary. | Exterior Elements | III | DM | Medium | \$80,000. |
| 2024 | Brevard Middle School | Remove aged and defective sealant joints and replace. Coordinate works with painting project. | Exterior Elements | III | DM | Medium | \$24,660. |
| 2024 | Brevard Middle School | Complete life safety and code evaluation. | Fire & Life Safety | III | CI | Medium | \$10,000. |
| 2024 | Brevard Middle School | Allowance for correcting potential air quality issues in the band and choir room. | Interiors | II | DM | High | \$50,000. |
| 2024 | Brevard Middle School | Replace stained and/or damaged ceiling tiles. | Interiors | III | DM | Low | \$16,000. |
| 2024 | Brevard Middle School | Complete indoor air quality testing in the band and choir room. | Interiors | II | DM | High | \$5,000. |
| 2024 | Brevard Middle School | Replace built-up roof with a TPO roof. | Roofing Systems | II | DM | High | \$1,820,170. |
| 2024 | Brevard Middle School | Repair concrete sidewalks, retaining walls, and planters. | Site Systems | III | CR | Medium | \$7,000. |
| 2024 | Brevard Middle School | Crack fill, seal coat and re-stripe asphalt pavement at the north lot. | Site Systems | III | DM | Medium | \$6,800. |
| 2024 | Brevard Middle School | Allowance for repairs to site brick planters and retaining walls. | Site Systems | III | DM | Low | \$6,000. |
| 2025 | Brevard Middle School | Allowance to improve school security systems and school safety. | Electrical | II | CI | High | \$328,510. |
| 2025 | Brevard Middle School | Replace the main fire alarm control panel along with the dialer, annunciator and as needed devices. | Fire & Life Safety | III | CR | High | \$50,000. |
| 2025 | Brevard Middle School | Construct vestibules per Physical Security Assessment. | Interiors | II | CI | High | \$187,720. |
| 2025 | Brevard Middle School | Replace heating hot water boiler. | Mechanical | III | CR | Medium | \$420,200. |
| 2025 | Brevard Middle School | Replace 1995 McQuay air handling unit. | Mechanical | III | CR | Medium | \$50,000. |
| 2025 | Brevard Middle School | Remove underground storage tank and install new above ground code/regulation compliant storage tank. | Plumbing | II | CR | High | \$175,000. |
| 2025 | Brevard Middle School | Install additional site fencing. | Site Systems | III | CI | Medium | \$36,000. |
| 2027 | Brevard Middle School | Replace 2009 PVI water heater. | Plumbing | III | CR | Medium | \$45,000. |
| 2028 | Brevard Middle School | Repaint all exterior painted elements including profiled metal panels and lintels. | Exterior Elements | III | SM | Medium | \$44,388. |
| 2029 | Brevard Middle School | Crack fill, seal coat and re-stripe asphalt, including ADA parking spaces and playground markings. | Site Systems | IV | SM | Low | \$24,220. |
| 2031 | Brevard Middle School | Replace asphalt shingle roofs. | Roofing Systems | IV | CR | Medium | \$69,582. |
| 2031 | Brevard Middle School | Mill and overlay the north parking lot. | Site Systems | IV | CR | Medium | \$74,800. |
| | | | | | | | \$4,339,430. |

Costs exclude design fees, permits, insurance, CM fees, etc.

Transylvania County Schools
Focus Projects
2024-2031

| Project Year | Building | Recommendation | System | Priority Category | Deficiency Category | Risk Category | Anticipated Cost |
|--------------|-----------------------|--|--------------------|-------------------|---------------------|---------------|-------------------|
| 2024 | Davidson River School | Excavate external perimeter of affected rooms and install French drain. | Interiors | III | DM | High | \$18,000. |
| 2024 | Davidson River School | Replace VCT flooring following water remediation work. | Interiors | III | DM | High | \$5,400. |
| 2024 | Davidson River School | Replace 3-ton split system unit. | Mechanical | III | CR | High | \$8,400. |
| 2024 | Davidson River School | Replace exterior handrails and guardrails | Site Systems | II | DM | High | \$10,450. |
| 2025 | Davidson River School | Allowance to improve school security systems and school safety. | Electrical | II | CI | High | \$81,936. |
| 2025 | Davidson River School | Repaint and repair all exterior painted elements. | Exterior Elements | III | SM | Medium | \$38,214. |
| 2025 | Davidson River School | Remove aged and defective sealant joints and replace. Coordinate with painting project. | Exterior Elements | III | SM | Medium | \$15,480. |
| 2025 | Davidson River School | Remove damaged stucco and replace. | Exterior Elements | III | DM | Medium | \$9,000. |
| 2025 | Davidson River School | Upgrade the fire alarm control panel and as needed devices | Fire & Life Safety | III | CR | High | \$15,000. |
| 2025 | Davidson River School | Construct vestibules per Physical Security Assessment. | Interiors | II | CI | High | \$54,624. |
| 2025 | Davidson River School | Replace VTAC unit with mini split system. | Mechanical | III | CR | Medium | \$7,500. |
| 2025 | Davidson River School | Install additional site fencing. | Site Systems | III | CI | Medium | \$36,000. |
| 2025 | Davidson River School | Mill and overlay asphalt paved sections due to surface deterioration | Site Systems | III | DM | Medium | \$21,000. |
| 2025 | Davidson River School | Allowance for site wide concrete and masonry repairs to site features, including steps. | Site Systems | III | DM | Medium | \$20,000. |
| 2026 | Davidson River School | Re-pave and restripe parking/ play area paint. | Site Systems | III | DM | Medium | \$9,280. |
| 2030 | Davidson River School | Replace asphalt shingle roof along with the gutters and downspouts. | Roofing Systems | IV | CR | Medium | \$90,000. |
| 2025 | Davidson River School | Remove underground storage tank and install new above ground code/regulation compliant storage tank. | Plumbing | III | CR | High | \$155,000. |
| 2031 | Davidson River School | Replace split system Carrier units. | Mechanical | III | CR | Medium | \$121,800. |
| | | | | | | | \$717,084. |

Costs exclude design fees, permits, insurance, CM fees, etc.

Transylvania County Schools
Focus Projects
2024-2031

| Project Year | Building | Recommendation | System | Priority Category | Deficiency Category | Risk Category | Anticipated Cost |
|--------------|-------------------------|--|-------------------|-------------------|---------------------|---------------|-------------------|
| 2024 | Morris Education Center | Complete minor updates and reconfigurations to bathrooms to achieve ADA compliance where possible. | Accessibility | VI | DM | Low | \$7,500. |
| 2024 | Morris Education Center | Repoint areas of cracked mortar across the exterior façades. | Exterior Elements | III | DM | Medium | \$11,250. |
| 2024 | Morris Education Center | Prepare metalwork to lintels and woodwork, and repaint/re-stain as necessary. | Exterior Elements | IV | SM | Low | \$3,800. |
| 2024 | Morris Education Center | Replace tile floor finishes to room and monitor exterior drains at outside stairwells. | Interiors | III | DM | Low | \$8,450. |
| 2024 | Morris Education Center | Install new metal guardrail at the southern exterior wall at the yard area. | Site Systems | II | DM | High | \$15,000. |
| 2024 | Morris Education Center | Crack fill, seal coat, and restripe the asphalt at the parking lot and driving lanes. | Site Systems | III | SM | Low | \$7,290. |
| 2024 | Morris Education Center | Complete repairs to entrance steps on north-facing elevation. | Site Systems | II | DM | High | \$6,500. |
| 2024 | Morris Education Center | Undertake repairs and repainting of metal site handrails. | Site Systems | III | SM | Low | \$5,000. |
| 2025 | Morris Education Center | Allowance to improve school security systems and school safety. | Electrical | II | CI | High | \$77,000. |
| 2031 | Morris Education Center | Mill and overlay the asphalt at the parking lot and driving lanes. | Site Systems | IV | CR | Low | \$36,450. |
| | | | | | | | \$178,240. |

Costs exclude design fees, permits, insurance, CM fees, etc.

Transylvania County Schools
Focus Projects
2024-2031

| Project Year | Building | Recommendation | System | Priority Category | Deficiency Category | Risk Category | Anticipated Cost |
|--------------|--------------------------|--|--------------------|-------------------|---------------------|---------------|------------------|
| 2024 | Pisgah Forest Elementary | Replace failed IGU's where necessary. | Exterior Elements | III | DM | Low | \$37,500. |
| 2024 | Pisgah Forest Elementary | Repaint exterior painted surfaces. | Exterior Elements | III | DM | Medium | \$30,500. |
| 2024 | Pisgah Forest Elementary | Replace exterior sealants. | Exterior Elements | III | DM | Medium | \$11,000. |
| 2024 | Pisgah Forest Elementary | Complete life safety and code evaluation. | Fire & Life Safety | III | CI | Medium | \$10,000. |
| 2024 | Pisgah Forest Elementary | Replace stained and/or damaged ceiling tiles. | Interiors | III | DM | Low | \$8,000. |
| 2024 | Pisgah Forest Elementary | Allowance for inspection and repair of asphalt shingle roof. | Roofing Systems | III | DM | Medium | \$10,000. |
| 2024 | Pisgah Forest Elementary | Allowance for rainwater gutter repairs and modifications. | Roofing Systems | III | DM | Medium | \$5,000. |
| 2024 | Pisgah Forest Elementary | Mill and overlay asphalt pavement - Phase 1 | Site Systems | III | DM | Medium | \$45,000. |
| 2024 | Pisgah Forest Elementary | Complete full depth repair and repavement of the dumpster and kitchen loading areas. | Site Systems | III | DM | Medium | \$28,000. |
| 2024 | Pisgah Forest Elementary | Replace localized sections of concrete sidewalks. | Site Systems | III | DM | Medium | \$5,625. |
| 2025 | Pisgah Forest Elementary | Upgrade the fire alarm control panel, annunciator panel, and as needed devices. | Fire & Life Safety | II | CR | Medium | \$25,000. |
| 2025 | Pisgah Forest Elementary | Replace McQuay air handling units. | Mechanical | III | CR | Medium | \$880,000. |
| 2025 | Pisgah Forest Elementary | Replace HVAC control system, including BMS upgrades. | Mechanical | III | CR | Medium | \$227,169. |
| 2025 | Pisgah Forest Elementary | Replace domestic water heater (125 gallon, 399,000 BTU/Hr.). | Plumbing | III | CR | Low | \$40,000. |
| 2025 | Pisgah Forest Elementary | Mill and overlay asphalt pavement - Phase 2 | Site Systems | III | CR | Medium | \$45,000. |
| 2025 | Pisgah Forest Elementary | Install additional site fencing. | Site Systems | III | CI | Medium | \$36,000. |
| 2026 | Pisgah Forest Elementary | Allowance to improve school security systems and school safety. | Electrical | III | CI | Medium | \$321,419. |
| 2026 | Pisgah Forest Elementary | Replace emergency generator and associated ATS. | Electrical | III | CR | Medium | \$15,000. |
| 2026 | Pisgah Forest Elementary | Mill and overlay asphalt pavement - Phase 3 | Site Systems | III | CR | Medium | \$45,000. |
| 2027 | Pisgah Forest Elementary | Replace platform lift. | Conveyance Systems | III | CR | Low | \$20,000. |
| 2027 | Pisgah Forest Elementary | Replace heating hot water boilers. | Mechanical | III | CR | Medium | \$298,760. |
| 2028 | Pisgah Forest Elementary | Replace playground equipment. | Site Systems | III | CR | Low | \$450,000. |
| 2029 | Pisgah Forest Elementary | Replace air-cooled chiller. | Mechanical | III | CR | Medium | \$240,000. |
| 2030 | Pisgah Forest Elementary | Remove underground storage tank and install new above ground code/regulation compliant storage tank. | Plumbing | IV | CR | Medium | \$175,000. |
| 2030 | Pisgah Forest Elementary | Crack fill, seal coat and restripe asphalt surfaces - Cycle 1 | Site Systems | IV | SM | Low | \$16,860. |
| | | | | | | | \$3,025,833. |

Costs exclude design fees, permits, insurance, CM fees, etc.

Transylvania County Schools
 Focus Projects
 2024-2031

| Project Year | Building | Recommendation | System | Priority Category | Deficiency Category | Risk Category | Anticipated Cost |
|--------------|------------------|--|-------------------|-------------------|---------------------|---------------|-------------------|
| 2024 | Plant Operations | Replace painted metal doors and frames. | Exterior Elements | II | DM | Medium | \$34,000. |
| 2024 | Plant Operations | Replace perimeter window and door sealants. | Exterior Elements | II | DM | Low | \$4,760. |
| 2024 | Plant Operations | Replace split system unit. | Mechanical | III | DM | Medium | \$5,600. |
| 2025 | Plant Operations | Replace Westinghouse electrical panels and other as needed components. | Electrical | III | CR | Low | \$122,796. |
| 2025 | Plant Operations | Provide life extension coating for the standing seam roof. | Roofing Systems | III | CR | Medium | \$12,000. |
| 2027 | Plant Operations | Refresh gravel paved areas | Site Systems | III | SM | Low | \$24,000. |
| 2029 | Plant Operations | Replace built-up roofing system down to the decking. Consideration over installing a TPO roof system should be reviewed. | Roofing Systems | III | CR | Low | \$198,000. |
| | | | | | | | \$401,156. |

Costs exclude design fees, permits, insurance, CM fees, etc.

Transylvania County Schools
Focus Projects
2024-2031

| Project Year | Building | Recommendation | System | Priority Category | Deficiency Category | Risk Category | Anticipated Cost |
|--------------|-------------------|--|--------------------|-------------------|---------------------|---------------|---------------------|
| 2024 | Rosman Elementary | Replace exterior sealant joints. | Exterior Elements | II | DM | High | \$14,000. |
| 2024 | Rosman Elementary | Upgrade fire alarm control panel, annunciator, and as needed devices. | Fire & Life Safety | II | CR | High | \$25,000. |
| 2026 | Rosman Elementary | Remove underground storage tank and install new above ground code/regulation compliant storage tank. | Plumbing | III | CR | Medium | \$175,000. |
| 2024 | Rosman Elementary | Fully strip off and replace the modified bitumen roof with a TPO membrane. | Roofing Systems | II | DM | High | \$740,000. |
| 2024 | Rosman Elementary | Clean existing roof and paint with a suitable metal paint. | Roofing Systems | III | SM | Low | \$18,900. |
| 2024 | Rosman Elementary | Replace athletic field bleachers. | Site Systems | III | DM | Low | \$13,500. |
| 2024 | Rosman Elementary | Refurbish athletic field structures. | Site Systems | III | DM | Low | \$10,000. |
| 2025 | Rosman Elementary | Upgrade 1974 vintage GE electrical panels. | Electrical | III | CR | Medium | \$424,000. |
| 2025 | Rosman Elementary | Allowance to improve school security systems and school safety. | Electrical | II | CI | High | \$225,250. |
| 2025 | Rosman Elementary | Install fire sprinkler system. | Fire & Life Safety | VI | CI | High | \$424,000. |
| 2025 | Rosman Elementary | Construct vestibules per Physical Security Assessment. | Interiors | II | CI | High | \$106,000. |
| 2025 | Rosman Elementary | Replace air handling units and associated ductwork. | Mechanical | III | CR | Medium | \$720,000. |
| 2025 | Rosman Elementary | Replace heating hot water boiler. | Mechanical | III | CR | Medium | \$247,280. |
| 2025 | Rosman Elementary | Upgrade BMS system. | Mechanical | III | CR | Medium | \$172,250. |
| 2025 | Rosman Elementary | Install additional site fencing. | Site Systems | III | CI | Medium | \$36,000. |
| 2026 | Rosman Elementary | Crack fill, seal coat, and restripe the parking lot and roadway areas. | Site Systems | III | SM | Low | \$18,330. |
| 2026 | Rosman Elementary | Crack fill and seal coat the path/walkway areas. | Site Systems | III | SM | Low | \$6,300. |
| 2028 | Rosman Elementary | Replace perimeter window sealant joints. | Exterior Elements | III | SM | Low | \$18,500. |
| 2028 | Rosman Elementary | Replace the asphalt roof shingles on a like-for-like basis. | Roofing Systems | III | CR | Medium | \$45,000. |
| 2030 | Rosman Elementary | Replace rooftop air-cooled chillers. | Mechanical | III | CR | Medium | \$468,000. |
| 2031 | Rosman Elementary | Replace 2017 PVI water heater. | Plumbing | IV | CR | Medium | \$45,000. |
| 2031 | Rosman Elementary | Replace playground equipment and swing set. | Site Systems | IV | CR | Low | \$500,000. |
| | | | | | | | \$4,452,310. |

Costs exclude design fees, permits, insurance, CM fees, etc.

Transylvania County Schools
Focus Projects
2024-2031

| Project Year | Building | Recommendation | System | Priority Category | Deficiency Category | Risk Category | Anticipated Cost |
|--------------|----------------------|--|--------------------|-------------------|---------------------|---------------|------------------|
| 2024 | Rosman Middle & High | Replace failed glazing units. | Exterior Elements | III | DM | Medium | \$110,000. |
| 2024 | Rosman Middle & High | Clean and recoat the EIFS. Includes allowance for repairs to the EIFS due to potential moisture damage. | Exterior Elements | III | DM | Medium | \$87,850. |
| 2024 | Rosman Middle & High | Replace elastomeric sealant joints across building exteriors. | Exterior Elements | III | DM | High | \$63,000. |
| 2024 | Rosman Middle & High | Complete life safety and code evaluation. | Fire & Life Safety | III | CI | Medium | \$15,000. |
| 2024 | Rosman Middle & High | Replace stained and/or damaged ceiling tiles. | Interiors | III | DM | Low | \$20,000. |
| 2024 | Rosman Middle & High | Phased replacement of air handling units. | Mechanical | III | CR | Medium | \$1,120,000. |
| 2024 | Rosman Middle & High | Phased replacement of unit ventilators. | Mechanical | III | CR | Medium | \$600,000. |
| 2024 | Rosman Middle & High | Replace air-cooled chiller outside the Cafeteria. | Mechanical | III | CR | High | \$462,000. |
| 2024 | Rosman Middle & High | Replace modified bitumen roof with new TPO roof at the High School. | Roofing Systems | II | DM | High | \$710,000. |
| 2024 | Rosman Middle & High | Replace modified bitumen with new TPO roof at the Middle School. | Roofing Systems | II | DM | High | \$264,000. |
| 2024 | Rosman Middle & High | Replace modified bitumen with new TPO roof at the Old Gym. | Roofing Systems | II | DM | High | \$228,000. |
| 2024 | Rosman Middle & High | Allowance for the evaluation and follow up repairs of the segmental retaining wall. | Site Systems | II | DM | High | \$715,000. |
| 2024 | Rosman Middle & High | The asphalt should be removed and full-depth asphalt repairs completed. | Site Systems | III | DM | Medium | \$59,500. |
| 2024 | Rosman Middle & High | Fully mill and overlay the asphalt behind the Old Gym and upper parking lot. | Site Systems | III | DM | Medium | \$49,500. |
| 2024 | Rosman Middle & High | Fully mill and overlay the asphalt behind the High School and below the Old Gym | Site Systems | III | DM | Medium | \$21,300. |
| 2024 | Rosman Middle & High | Replace damaged sections of chain link fencing. | Site Systems | III | DM | Medium | \$9,000. |
| 2024 | Rosman Middle & High | Further investigation by a Structural Engineer and provisional placeholder cost for repair works recommended. | Structural Systems | II | DM | High | \$165,000. |
| 2025 | Rosman Middle & High | Modernize hydraulic elevator. | Conveyance Systems | III | CR | Medium | \$200,000. |
| 2025 | Rosman Middle & High | Allowance to improve school security systems and school safety. | Electrical | II | CI | High | \$457,828. |
| 2025 | Rosman Middle & High | Complete exterior repairs. Cycle one. | Exterior Elements | III | SM | Medium | \$75,000. |
| 2025 | Rosman Middle & High | Replace Fieldhouse fire alarm control panel. | Fire & Life Safety | III | CR | Medium | \$20,000. |
| 2025 | Rosman Middle & High | Construct vestibules per Physical Security Assessment. | Interiors | II | CI | High | \$281,740. |
| 2025 | Rosman Middle & High | Allowance to complete a detailed indoor air quality study and provisional placeholder cost for repair works recommended. | Mechanical | III | CI | Medium | \$750,000. |
| 2025 | Rosman Middle & High | Upgrade BMS system. | Mechanical | III | CR | Medium | \$387,393. |
| 2025 | Rosman Middle & High | Complete study, design, and construction of a stormwater management system at the football field. | Site Systems | III | CI | Medium | \$1,925,000. |
| 2025 | Rosman Middle & High | Replace damaged concrete at the amphitheater. | Site Systems | III | CR | Low | \$7,000. |
| 2026 | Rosman Middle & High | Upgrade antiquated electrical panels throughout the building. | Electrical | III | CR | Medium | \$216,000. |
| 2026 | Rosman Middle & High | Refurbish Boiler #3 along with associated pumps, valves, and accessories. | Mechanical | III | SM | Medium | \$184,800. |

Costs exclude design fees, permits, insurance, CM fees, etc.

Transylvania County Schools
 Focus Projects
 2024-2031

| Project Year | Building | Recommendation | System | Priority Category | Deficiency Category | Risk Category | Anticipated Cost |
|--------------|----------------------|--|-------------------|-------------------|---------------------|---------------|----------------------|
| 2026 | Rosman Middle & High | Replace Boiler #4 along with associated pumps, valves, and accessories. | Mechanical | III | CR | Medium | \$119,240. |
| 2026 | Rosman Middle & High | Replace PVI water heater #1 and #2 | Plumbing | III | CR | Medium | \$110,000. |
| 2026 | Rosman Middle & High | Replace 250-gallon electric water heater. | Plumbing | III | CR | Medium | \$45,000. |
| 2027 | Rosman Middle & High | Remove underground storage tank and install new above ground code/regulation compliant storage tank. | Plumbing | III | CR | Medium | \$265,000. |
| 2028 | Rosman Middle & High | Replace Boiler #1 and #2 along with associated pumps, valves, and accessories. | Mechanical | III | CR | Medium | \$451,000. |
| 2028 | Rosman Middle & High | Crack fill, seal coat, and restripe asphalt (future cycle on asphalt which has been replaced). | Site Systems | IV | SM | Low | \$12,840. |
| 2030 | Rosman Middle & High | Complete exterior repairs. Cycle two. | Exterior Elements | IV | SM | Medium | \$50,000. |
| 2031 | Rosman Middle & High | Replace the Fieldhouse package units. | Mechanical | III | CR | Medium | \$80,000. |
| | | | | | | | \$10,336,991. |

Costs exclude design fees, permits, insurance, CM fees, etc.

Transylvania County Schools
Focus Projects
2024-2031

| Project Year | Building | Recommendation | System | Priority Category | Deficiency Category | Risk Category | Anticipated Cost |
|--------------|-------------------------|---|--------------------|-------------------|---------------------|---------------|---------------------|
| 2024 | TC Henderson Elementary | Replace air handling units. | Mechanical | III | CR | Medium | \$225,000. |
| 2024 | TC Henderson Elementary | Replace cabinet fan coil units. | Mechanical | III | CR | Medium | \$108,000. |
| 2024 | TC Henderson Elementary | Upgrade HVAC control system. | Mechanical | III | CR | Medium | \$91,000. |
| 2024 | TC Henderson Elementary | Replace 10-ton McQuay and 2-ton split systems. | Mechanical | III | CR | Medium | \$82,500. |
| 2024 | TC Henderson Elementary | Replace 5-ton ICS split system. | Mechanical | III | CR | Medium | \$18,750. |
| 2024 | TC Henderson Elementary | Mill and overlay asphalt paved sections. | Site Systems | II | DM | Medium | \$78,000. |
| 2024 | TC Henderson Elementary | Replace door, removable roof system, and paint exterior walls. | Site Systems | II | DM | High | \$12,000. |
| 2024 | TC Henderson Elementary | Allowance for repairs to the pedestrian bridge | Site Systems | III | DM | Medium | \$3,500. |
| 2025 | TC Henderson Elementary | Allowance to improve school security systems and school safety. | Electrical | II | CI | High | \$168,000. |
| 2025 | TC Henderson Elementary | Repaint all exterior painted elements including profiled metal sheeting, gutters, downpipes, lintels, and canopies. | Exterior Elements | III | SM | Medium | \$51,660. |
| 2025 | TC Henderson Elementary | Replace caulk seals to perimeter of windows and doors - Cycle 1. | Exterior Elements | III | DM | Medium | \$15,000. |
| 2025 | TC Henderson Elementary | Construct vestibules per Physical Security Assessment. | Interiors | II | CI | High | \$84,000. |
| 2025 | TC Henderson Elementary | Install additional site fencing. | Site Systems | III | CI | Medium | \$36,000. |
| 2026 | TC Henderson Elementary | Replace PVI water heater. | Plumbing | III | CR | Medium | \$40,000. |
| 2026 | TC Henderson Elementary | Remove underground storage tank and install new above ground code/regulation compliant storage tank. | Plumbing | III | CR | Medium | \$110,000. |
| 2026 | TC Henderson Elementary | Remove modified bitumen roof and replace with TPO roof covering. | Roofing Systems | III | CR | Medium | \$21,200. |
| 2027 | TC Henderson Elementary | Replace/upgrade the fire alarm control panel, annunciator panel, and as needed devices. | Fire & Life Safety | III | CR | Medium | \$20,000. |
| 2028 | TC Henderson Elementary | Replace heating hot water boiler. | Mechanical | III | CR | Medium | \$118,470. |
| 2028 | TC Henderson Elementary | Allowance for as needed well system replacements. | Plumbing | III | CR | Low | \$15,000. |
| 2028 | TC Henderson Elementary | Replace metal roof along with the gutters and downspouts. | Roofing Systems | III | CR | Medium | \$363,000. |
| 2029 | TC Henderson Elementary | Replace playground equipment. | Site Systems | III | CR | Low | \$200,000. |
| Total | | | | | | | \$1,861,080. |

Costs exclude design fees, permits, insurance, CM fees, etc.

REPORT OF FACILITY CONDITION ASSESSMENT



Brevard High School

Property Address:

609 N Country Club Rd
Brevard, NC 28712

Prepared For:

Transylvania County
Board of Commissioners
101 South Broad Street
Brevard, NC 28712

Prepared By:

Axias
Project No. GA23-017
February 26, 2024


| Item No. | Condition | Recommendation | Priority Category | Deficiency Category | Impact of Failure | Condition | Probability of Failure | Frequency of Failure | Risk Score | Risk Category | Estimated Useful Life | Remaining Useful Life | Quantity | Unit of Measure | Unit Cost | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | Required | |
|---------------------------|--|--|-------------------|---------------------|-------------------|-----------|------------------------|----------------------|------------|---------------|-----------------------|-----------------------|----------|-----------------|-----------|-----------|------|------|------|------|------|------|------|------|------|-----------|-----------|
| 9 | The football field consists of an artificial turf field. These types of field typically have a service life of 10-12 years depending on use and maintenance. The turf was replaced in 2023. It is recommended to budget for the replacement of the turf field during the study period. | Replace artificial turf field. | IV | CR | 4 | 3 | 4 | 4 | 15 | Medium | 10 | 10 | 74,000 | SF | \$8.00 | | | | | | | | | | | \$592,000 | |
| 10 | The softball field is provided with field lighting mounted on treated wood poles. The lighting appeared to be in poor to fair condition with deterioration noted. It is recommended to replace the softball field lighting. | Replace softball field lighting. | III | CR | 4 | 3 | 4 | 4 | 15 | Medium | 25 | 2 | 4 | EA | \$30,000 | \$120,000 | | | | | | | | | | \$120,000 | |
| 11 | Select dugouts are constructed into the side of the adjacent grade with the majority of the concrete masonry unit walls being below grade. Evidence of water infiltration through the walls was noted. Over time this can lead to deterioration of the mortar joints and concrete masonry units. It is recommended to excavate behind the dugout walls and apply a waterproofing membrane to prevent further water infiltration. A stone backfill should also be provided along with the installation of a foundation drain pipe to direct water away from the dugout. | Provide waterproofing membrane at concrete masonry unit walls of the dugouts. | III | DM | 3 | 3 | 4 | 4 | 14 | Medium | 25 | 1 | 3 | EA | \$12,000 | \$36,000 | | | | | | | | | | \$36,000 | |
| Structural Systems | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Required | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 1 | Dampness and cracking to plaster finishes in the Auditorium was observed on either side (north and south) being 25' to 30' deep. The finishes are understood to be below grade. | Excavate externally and replace failed areas of surface concrete. Remove damaged plaster internally and repaint. | II | DM | 4 | 2 | 4 | 4 | 14 | Medium | 20 | 1 | 750 | SF | \$150.00 | \$112,500 | | | | | | | | | | | \$112,500 |
| Roofing Systems | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Required | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 1 | The standing seam metal roof above the Media Center/Guidance is original to the building and is in poor condition, with water ingress a common occurrence. A section of the roof has been overlaid with rigid insulation and a TPO membrane, over the top of the original roof. | Replace standing seam metal roof at Media Center/Guidance wing. | II | DM | 3 | 2 | 2 | 3 | 10 | High | 25 | 1 | 12,900 | SF | \$35.00 | \$451,500 | | | | | | | | | | | \$451,500 |
| 2 | The low slope roof at the EC Wing (lower roof) was noted to be in very poor condition. The roof membrane is severely deteriorated and large areas of debris and standing water were noted. | Replace roof at EC wing with TPO membrane. | II | DM | 3 | 1 | 2 | 3 | 9 | High | 20 | 1 | 3,150 | SF | \$22.00 | \$69,300 | | | | | | | | | | | \$69,300 |
| 3 | The small section of TPO low-slope roof at the Science Building Foyer is in poor condition and reportedly leaks often. The roof has been coated and repaired several times, but continues to leak. | Replace roof at Science Building Foyer with TPO membrane. | II | DM | 4 | 2 | 3 | 3 | 12 | High | 20 | 1 | 450 | SF | \$22.00 | \$9,900 | | | | | | | | | | | \$9,900 |

Building: Breasted High School
 GAF: 1509 164 West, also, upline are additions
 Address: 609 N Country Club Rd
 Breard, IL 62112



| Item No. | Condition | Recommendation | Priority Category | Deficiency Category | Impact of Failure | Condition | Probability of Failure | Frequency of Failure | Risk Score | Risk Category | Estimated Useful Life | Remaining Useful Life | Quantity | Unit of Measure | Unit Cost | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | Required |
|----------|---|---|-------------------|---------------------|-------------------|-----------|------------------------|----------------------|------------|---------------|-----------------------|-----------------------|----------|-----------------|-----------|-----------|------|------|------|------|------|------|------|------|------|-----------|
| 4 | The Old Gym roof is in a state of failure. The TPO covering is at the end of its life and several areas of the wood tongue and groove wood roof deck have rotted away. At several locations, the deck has fallen to the ground or been removed. Other areas of the deck still in place appear to be saturated and are in a poor condition. Costs for removing and replacing the existing roof and installing a new standing seam metal roof are being estimated. Repairs of the roof deck once roof repairs are undertaken. | Replace roof to Old Gym with new TPO membrane, including as needed roof decking replacements. | II | DM | 3 | 2 | 2 | 3 | 10 | High | 20 | 1 | 13,500 | SF | \$40.00 | \$540,000 | | | | | | | | | | \$540,000 |
| 5 | The standing seam metal roofs to the Gym Foyer and Old Gym Locker rooms (including outside restrooms) are original to the building and at the end of their useful life. At these areas of the building are connected to the Old Gym structure, works should only be completed if the gym is decided to be kept in use. | Replace standing seam metal roof coverings. | II | DM | 3 | 2 | 2 | 3 | 10 | High | 25 | 1 | 7,750 | SF | \$40.00 | \$310,000 | | | | | | | | | | \$310,000 |
| 6 | The roof at the Band Room and Band/Drama Rooms consists of a standing seam metal roof, and two lower roofs with an EPDM membrane and integral box gutters. The standing seam metal roof is original to the building and is in a poor to fair condition. When the roof is replaced, if possible, the box gutters should be framed out, so the roof is level and drains to interior leaders, simplifying the roof design. | Replace EPDM and standing seam metal roofs at the Band/Drama Rooms | III | CR | 4 | 3 | 3 | 4 | 14 | Medium | 25 | 2 | 4,500 | SF | \$40.00 | \$180,000 | | | | | | | | | | \$180,000 |
| 7 | The roof at the Vocational Wing and CTE Welding/Masonry building consist of modified bitumen roofs which were in a poor to fair condition. The roofs are at the end of their life and joints have been resealed/respiced at various points across the roofs. The existing standing seam roof system is fully stripped off and a new TPO roof system is installed. | Replace the roof at the Vocational Wing and CTE Welding/Masonry | III | CR | 4 | 3 | 4 | 4 | 15 | Medium | 20 | 3 | 32,800 | SF | \$22.00 | \$721,600 | | | | | | | | | | \$721,600 |
| 8 | The standing seam metal roof above the Math Wing is original to the building and in a poor condition. Recommend removing the roof covering and replacing with a new standing seam metal roof covering. | Replace standing seam metal roof at the Math Wing. | II | DM | 3 | 2 | 2 | 3 | 10 | High | 25 | 1 | 12,360 | SF | \$40.00 | \$494,400 | | | | | | | | | | \$494,400 |
| 9 | The standing seam metal roof above the English Wing and Office Area are original to the building and in a fair condition, but approaching the end of their life. Recommend removing the roof coverings and replacing with a new standing seam metal roof covering. | Replace standing seam metal roof at the English Wing and Office Area. | IV | CR | 5 | 3 | 4 | 5 | 17 | Low | 25 | 7 | 17,685 | SF | \$40.00 | \$707,400 | | | | | | | | | | \$707,400 |


Brewer High School
 Building:
 1955 (64 years), plus varying size additions
 609 N. Country Club Rd
 Address:
 Bremond, TX 78011



AXIAS
 BUILDING VALUE

| Item No. | Condition | Recommendation | Priority | Category | Order | Impact of Failure | Condition | Probability of Failure | Frequency of Failure | Risk Score | Risk Category | Estimated Useful Life | Remaining Useful Life | Quantity | Unit of Measure | Unit Cost | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | Required | |
|----------|---|---|----------|----------|-------|-------------------|-----------|------------------------|----------------------|------------|---------------|-----------------------|-----------------------|----------|-----------------|-----------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|----------|-----------|
| 3 | Deterioration to the exterior curved glulam wood beams at the Cafeteria have deteriorated. Structural repairs have been completed at the bases of the beams to strengthen the beams and works have been completed, per drawings and documents produced by Medlock Associates. However, paint finishes to the beams are in poor condition. Paint is flaking or missing across all beams, exposing the wood and its health which is deteriorating. The beams are further deteriorating to the wood beams. Costs for this item could fluctuate based on the condition of the wood beams once renovation works begin. | Surface prep glulam beams and repaint the exposed exterior beams with a suitable exterior wood paint. | III | DM | 3 | 2 | 3 | 4 | 12 | High | 10 | 1 | 1,200 | SF | \$15.00 | \$18,000 | | | | | | | | | | | | | | | | | | | \$18,000 |
| 4 | High level windows at the Old Gym and Old Gym Locker Rooms are in poor condition. Sealant joints at the perimeter of the windows have perished and several of the panes are cracked. As detailed elsewhere in this cost table, works should only be completed once the long-term future of the building has been decided. | Replace high level windows at the Old Gym and Old Gym Locker Rooms. | III | DM | 4 | 2 | 3 | 11 | High | 25 | 1 | 1,400 | SF | \$120.00 | \$168,000 | | | | | | | | | | | | | | | | | | | | \$168,000 |
| 5 | Deterioration to the exterior curved glulam wood beams at the Old Gym have deteriorated. Structural repairs have been completed at the bases of the beams to strengthen the beams and works have been completed, per drawings and documents produced by Medlock Associates. However, paint finishes to the beams are in poor condition. Paint is flaking or missing across all beams, exposing the wood underneath which if left unaddressed will result in further deterioration to the wood beams. Costs for this item could fluctuate based on the condition of the wood beams once renovation works begin. | Surface prep glulam beams and repaint the exposed exterior beams with a suitable exterior wood paint. | II | DM | 3 | 2 | 3 | 4 | 12 | High | 10 | 1 | 3,600 | SF | \$15.00 | \$54,000 | | | | | | | | | | | | | | | | | | | \$54,000 |
| 6 | Brickwork to the Old Gym was stained, mortar joints were missing, and sealant joints at movement joints had perished. Recommend exterior masonry project to repair defective masonry including repointing, cleaning of stained brickwork, and replacement of failed sealant joints. As detailed elsewhere in this cost table, works should only be completed once the long-term future of the building has been decided. | Complete masonry restoration and repairs at the Old Gym. | III | DM | 3 | 2 | 3 | 3 | 11 | High | 20 | 1 | 3,750 | SF | \$95 | \$356,250 | | | | | | | | | | | | | | | | | | | \$356,250 |

Building:
Address:
 Brewood High School
 1555 (44) 1555, plus workshop additions
 609 N Country Club Rd
 Brewood, NC 28712



AXIAS
 BUILDING VALUE

| <p>AXIOS BUILDING VALUE</p> <p>Breyard High School 1555 Oak Vista plus working site additions 609 W Country Club Rd Brevard, NC 28712</p> | | | | | | | | | | | | Year | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 | 2046 | 2047 | 2048 | 2049 | 2050 | 2051 | 2052 | 2053 | 2054 | 2055 | 2056 | 2057 | 2058 | 2059 | 2060 | 2061 | 2062 | 2063 | 2064 | 2065 | 2066 | 2067 | 2068 | 2069 | 2070 | 2071 | 2072 | 2073 | 2074 | 2075 | 2076 | 2077 | 2078 | 2079 | 2080 | 2081 | 2082 | 2083 | 2084 | 2085 | 2086 | 2087 | 2088 | 2089 | 2090 | 2091 | 2092 | 2093 | 2094 | 2095 | 2096 | 2097 | 2098 | 2099 | 2100 | 2101 | 2102 | 2103 | 2104 | 2105 | 2106 | 2107 | 2108 | 2109 | 2110 | 2111 | 2112 | 2113 | 2114 | 2115 | 2116 | 2117 | 2118 | 2119 | 2120 | 2121 | 2122 | 2123 | 2124 | 2125 | 2126 | 2127 | 2128 | 2129 | 2130 | 2131 | 2132 | 2133 | 2134 | 2135 | 2136 | 2137 | 2138 | 2139 | 2140 | 2141 | 2142 | 2143 | 2144 | 2145 | 2146 | 2147 | 2148 | 2149 | 2150 | 2151 | 2152 | 2153 | 2154 | 2155 | 2156 | 2157 | 2158 | 2159 | 2160 | 2161 | 2162 | 2163 | 2164 | 2165 | 2166 | 2167 | 2168 | 2169 | 2170 | 2171 | 2172 | 2173 | 2174 | 2175 | 2176 | 2177 | 2178 | 2179 | 2180 | 2181 | 2182 | 2183 | 2184 | 2185 | 2186 | 2187 | 2188 | 2189 | 2190 | 2191 | 2192 | 2193 | 2194 | 2195 | 2196 | 2197 | 2198 | 2199 | 2200 | 2201 | 2202 | 2203 | 2204 | 2205 | 2206 | 2207 | 2208 | 2209 | 2210 | 2211 | 2212 | 2213 | 2214 | 2215 | 2216 | 2217 | 2218 | 2219 | 2220 | 2221 | 2222 | 2223 | 2224 | 2225 | 2226 | 2227 | 2228 | 2229 | 2230 | 2231 | 2232 | 2233 | 2234 | 2235 | 2236 | 2237 | 2238 | 2239 | 2240 | 2241 | 2242 | 2243 | 2244 | 2245 | 2246 | 2247 | 2248 | 2249 | 2250 | 2251 | 2252 | 2253 | 2254 | 2255 | 2256 | 2257 | 2258 | 2259 | 2260 | 2261 | 2262 | 2263 | 2264 | 2265 | 2266 | 2267 | 2268 | 2269 | 2270 | 2271 | 2272 | 2273 | 2274 | 2275 | 2276 | 2277 | 2278 | 2279 | 2280 | 2281 | 2282 | 2283 | 2284 | 2285 | 2286 | 2287 | 2288 | 2289 | 2290 | 2291 | 2292 | 2293 | 2294 | 2295 | 2296 | 2297 | 2298 | 2299 | 2300 | 2301 | 2302 | 2303 | 2304 | 2305 | 2306 | 2307 | 2308 | 2309 | 2310 | 2311 | 2312 | 2313 | 2314 | 2315 | 2316 | 2317 | 2318 | 2319 | 2320 | 2321 | 2322 | 2323 | 2324 | 2325 | 2326 | 2327 | 2328 | 2329 | 2330 | 2331 | 2332 | 2333 | 2334 | 2335 | 2336 | 2337 | 2338 | 2339 | 2340 | 2341 | 2342 | 2343 | 2344 | 2345 | 2346 | 2347 | 2348 | 2349 | 2350 | 2351 | 2352 | 2353 | 2354 | 2355 | 2356 | 2357 | 2358 | 2359 | 2360 | 2361 | 2362 | 2363 | 2364 | 2365 | 2366 | 2367 | 2368 | 2369 | 2370 | 2371 | 2372 | 2373 | 2374 | 2375 | 2376 | 2377 | 2378 | 2379 | 2380 | 2381 | 2382 | 2383 | 2384 | 2385 | 2386 | 2387 | 2388 | 2389 | 2390 | 2391 | 2392 | 2393 | 2394 | 2395 | 2396 | 2397 | 2398 | 2399 | 2400 | 2401 | 2402 | 2403 | 2404 | 2405 | 2406 | 2407 | 2408 | 2409 | 2410 | 2411 | 2412 | 2413 | 2414 | 2415 | 2416 | 2417 | 2418 | 2419 | 2420 | 2421 | 2422 | 2423 | 2424 | 2425 | 2426 | 2427 | 2428 | 2429 | 2430 | 2431 | 2432 | 2433 | 2434 | 2435 | 2436 | 2437 | 2438 | 2439 | 2440 | 2441 | 2442 | 2443 | 2444 | 2445 | 2446 | 2447 | 2448 | 2449 | 2450 | 2451 | 2452 | 2453 | 2454 | 2455 | 2456 | 2457 | 2458 | 2459 | 2460 | 2461 | 2462 | 2463 | 2464 | 2465 | 2466 | 2467 | 2468 | 2469 | 2470 | 2471 | 2472 | 2473 | 2474 | 2475 | 2476 | 2477 | 2478 | 2479 | 2480 | 2481 | 2482 | 2483 | 2484 | 2485 | 2486 | 2487 | 2488 | 2489 | 2490 | 2491 | 2492 | 2493 | 2494 | 2495 | 2496 | 2497 | 2498 | 2499 | 2500 | 2501 | 2502 | 2503 | 2504 | 2505 | 2506 | 2507 | 2508 | 2509 | 2510 | 2511 | 2512 | 2513 | 2514 | 2515 | 2516 | 2517 | 2518 | 2519 | 2520 | 2521 | 2522 | 2523 | 2524 | 2525 | 2526 | 2527 | 2528 | 2529 | 2530 | 2531 | 2532 | 2533 | 2534 | 2535 | 2536 | 2537 | 2538 | 2539 | 2540 | 2541 | 2542 | 2543 | 2544 | 2545 | 2546 | 2547 | 2548 | 2549 | 2550 | 2551 | 2552 | 2553 | 2554 | 2555 | 2556 | 2557 | 2558 | 2559 | 2560 | 2561 | 2562 | 2563 | 2564 | 2565 | 2566 | 2567 | 2568 | 2569 | 2570 | 2571 | 2572 | 2573 | 2574 | 2575 | 2576 | 2577 | 2578 | 2579 | 2580 | 2581 | 2582 | 2583 | 2584 | 2585 | 2586 | 2587 | 2588 | 2589 | 2590 | 2591 | 2592 | 2593 | 2594 | 2595 | 2596 | 2597 | 2598 | 2599 | 2600 | 2601 | 2602 | 2603 | 2604 | 2605 | 2606 | 2607 | 2608 | 2609 | 2610 | 2611 | 2612 | 2613 | 2614 | 2615 | 2616 | 2617 | 2618 | 2619 | 2620 | 2621 | 2622 | 2623 | 2624 | 2625 | 2626 | 2627 | 2628 | 2629 | 2630 | 2631 | 2632 | 2633 | 2634 | 2635 | 2636 | 2637 | 2638 | 2639 | 2640 | 2641 | 2642 | 2643 | 2644 | 2645 | 2646 | 2647 | 2648 | 2649 | 2650 | 2651 | 2652 | 2653 | 2654 | 2655 | 2656 | 2657 | 2658 | 2659 | 2660 | 2661 | 2662 | 2663 | 2664 | 2665 | 2666 | 2667 | 2668 | 2669 | 2670 | 2671 | 2672 | 2673 | 2674 | 2675 | 2676 | 2677 | 2678 | 2679 | 2680 | 2681 | 2682 | 2683 | 2684 | 2685 | 2686 | 2687 | 2688 | 2689 | 2690 | 2691 | 2692 | 2693 | 2694 | 2695 | 2696 | 2697 | 2698 | 2699 | 2700 | 2701 | 2702 | 2703 | 2704 | 2705 | 2706 | 2707 | 2708 | 2709 | 2710 | 2711 | 2712 | 2713 | 2714 | 2715 | 2716 | 2717 | 2718 | 2719 | 2720 | 2721 | 2722 | 2723 | 2724 | 2725 | 2726 | 2727 | 2728 | 2729 | 2730 | 2731 | 2732 | 2733 | 2734 | 2735 | 2736 | 2737 | 2738 | 2739 | 2740 | 2741 | 2742 | 2743 | 2744 | 2745 | 2746 | 2747 | 2748 | 2749 | 2750 | 2751 | 2752 | 2753 | 2754 | 2755 | 2756 | 2757 | 2758 | 2759 | 2760 | 2761 | 2762 | 2763 | 2764 | 2765 | 2766 | 2767 | 2768 | 2769 | 2770 | 2771 | 2772 | 2773 | 2774 | 2775 | 2776 | 2777 | 2778 | 2779 | 2780 | 2781 | 2782 | 2783 | 2784 | 2785 | 2786 | 2787 | 2788 | 2789 | 2790 | 2791 | 2792 | 2793 | 2794 | 2795 | 2796 | 2797 | 2798 | 2799 | 2800 | 2801 | 2802 | 2803 | 2804 | 2805 | 2806 | 2807 | 2808 | 2809 | 2810 | 2811 | 2812 | 2813 | 2814 | 2815 | 2816 | 2817 | 2818 | 2819 | 2820 | 2821 | 2822 | 2823 | 2824 | 2825 | 2826 | 2827 | 2828 | 2829 | 2830 | 2831 | 2832 | 2833 | 2834 | 2835 | 2836 | 2837 | 2838 | 2839 | 2840 | 2841 | 2842 | 2843 | 2844 | 2845 | 2846 | 2847 | 2848 | 2849 | 2850 | 2851 | 2852 | 2853 | 2854 | 2855 | 2856 | 2857 | 2858 | 2859 | 2860 | 2861 | 2862 | 2863 | 2864 | 2865 | 2866 | 2867 | 2868 | 2869 | 2870 | 2871 | 2872 | 2873 | 2874 | 2875 | 2876 | 2877 | 2878 | 2879 | 2880 | 2881 | 2882 | 2883 | 2884 | 2885 | 2886 | 2887 | 2888 | 2889 | 2890 | 2891 | 2892 | 2893 | 2894 | 2895 | 2896 | 2897 | 2898 | 2899 | 2900 | 2901 | 2902 | 2903 | 2904 | 2905 | 2906 | 2907 | 2908 | 2909 | 2910 | 2911 | 2912 | 2913 | 2914 | 2915 | 2916 | 2917 | 2918 | 2919 | 2920 | 2921 | 2922 | 2923 | 2924 | 2925 | 2926 | 2927 | 2928 | 2929 | 2930 | 2931 | 2932 | 2933 | 2934 | 2935 | 2936 | 2937 | 2938 | 2939 | 2940 | 2941 | 2942 | 2943 | 2944 | 2945 | 2946 | 2947 | 2948 | 2949 | 2950 | 2951 | 2952 | 2953 | 2954 | 2955 | 2956 | 2957 | 2958 | 2959 | 2960 | 2961 | 2962 | 2963 | 2964 | 2965 | 2966 | 2967 | 2968 | 2969 | 2970 | 2971 | 2972 | 2973 | 2974 | 2975 | 2976 | 2977 | 2978 | 2979 | 2980 | 2981 | 2982 | 2983 | 2984 | 2985 | 2986 | 2987 | 2988 | 2989 | 2990 | 2991 | 2992 | 2993 | 2994 | 2995 | 2996 | 2997 | 2998 | 2999 | 3000 |
|---|-----------|----------------|----------|----------|-------|-----------|---------|-------------|-----------|------------|---------------|-----------------------|-----------------------|----------|-----------------|-----------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|
| Item No. | Condition | Recommendation | Priority | Category | Order | Condition | Failure | Probability | Frequency | Risk Score | Risk Category | Estimated Useful Life | Remaining Useful Life | Quantity | Unit of Measure | Unit Cost | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 | 2046 | 2047 | 2048 | 2049 | 2050 | 2051 | 2052 | 2053 | 2054 | 2055 | 2056 | 2057 | 2058 | 2059 | 2060 | 2061 | 2062 | 2063 | 2064 | 2065 | 2066 | 2067 | 2068 | 2069 | 2070 | 2071 | 2072 | 2073 | 2074 | 2075 | 2076 | 2077 | 2078 | 2079 | 2080 | 2081 | 2082 | 2083 | 2084 | 2085 | 2086 | 2087 | 2088 | 2089 | 2090 | 2091 | 2092 | 2093 | 2094 | 2095 | 2096 | 2097 | 2098 | 2099 | 2100 | 2101 | 2102 | 2103 | 2104 | 2105 | 2106 | 2107 | 2108 | 2109 | 2110 | 2111 | 2112 | 2113 | 2114 | 2115 | 2116 | 2117 | 2118 | 2119 | 2120 | 2121 | 2122 | 2123 | 2124 | 2125 | 2126 | 2127 | 2128 | 2129 | 2130 | 2131 | 2132 | 2133 | 2134 | 2135 | 2136 | 2137 | 2138 | 2139 | 2140 | 2141 | 2142 | 2143 | 2144 | 2145 | 2146 | 2147 | 2148 | 2149 | 2150 | 2151 | 2152 | 2153 | 2154 | 2155 | 2156 | 2157 | 2158 | 2159 | 2160 | 2161 | 2162 | 2163 | 2164 | 2165 | 2166 | 2167 | 2168 | 2169 | 2170 | 2171 | 2172 | 2173 | 2174 | 2175 | 2176 | 2177 | 2178 | 2179 | 2180 | 2181 | 2182 | 2183 | 2184 | 2185 | 2186 | 2187 | 2188 | 2189 | 2190 | 2191 | 2192 | 2193 | 2194 | 2195 | 2196 | 2197 | 2198 | 2199 | 2200 | 2201 | 2202 | 2203 | 2204 | 2205 | 2206 | 2207 | 2208 | 2209 | 2210 | 2211 | 2212 | 2213 | 2214 | 2215 | 2216 | 2217 | 2218 | 2219 | 2220 | 2221 | 2222 | 2223 | 2224 | 2225 | 2226 | 2227 | 2228 | 2229 | 2230 | 2231 | 2232 | 2233 | 2234 | 2235 | 2236 | 2237 | 2238 | 2239 | 2240 | 2241 | 2242 | 2243 | 2244 | 2245 | 2246 | 2247 | 2248 | 2249 | 2250 | 2251 | 2252 | 2253 | 2254 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

| Building: Brevard High School Address: 1250 14th Street, plus various additions Address: 609 N. Country Club Rd Brevard, FL 32712 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|--|--|---|----------|----------|-------|-------------------|-----------|------------------------|----------------------|------------|---------------|-----------------------|-----------------------|----------|-----------------|-----------|------|------|------|-----------|-----------|------|------|------|-----------|------|------|----------|-----------|
| Item No. | Condition | Recommendation | Priority | Category | Order | Impact of Failure | Condition | Probability of Failure | Frequency of Failure | Risk Score | Risk Category | Estimated Useful Life | Remaining Useful Life | Quantity | Unit of Measure | Unit Cost | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | Required | |
| 2 | Pad-mounted Chiller #2 located at the north wing and serving the Auditorium, Cafeteria, Office, History, Social Studies, and Band wing, was in fair condition. The chiller remains operational but will soon reach the end of its recommended useful life. | Replace pad mounted Chiller #2 at the north wing. | III | CR | 3 | 3 | 4 | 4 | 4 | 14 | Medium | 25 | 5 | 70 | TON | \$4,200 | | | | | \$294,000 | | | | | | | | \$294,000 |
| 3 | The roof-mounted chillers serving the Vocational wing were in fair condition. The chillers were replaced with new units and the electrical control interfaces and was not running at the time of the site visit. | Replace roof mounted chillers serving the Vocational wing. | III | CR | 3 | 3 | 4 | 4 | 4 | 14 | Medium | 25 | 5 | 70 | TON | \$4,500 | | | | | \$315,000 | | | | | | | | \$315,000 |
| 4 | Boilers #1 and #2 at the south corner of the Science wing and Boiler #4 at the south corner of the New Gym is in fair to good condition. The boilers have exceeded their recommended useful life and should be budgeted for replacement during the term. | Replace Boiler #1 and #2 along with associated controls, valves, etc. | III | CR | 3 | 4 | 4 | 5 | 16 | Medium | 30 | 5 | 1,158 | MBH | \$110 | | | | | | \$127,380 | | | | | | | | \$127,380 |
| 5 | Boilers #1 and #2 at the south corner of the Science wing and Boiler #4 at the south corner of the New Gym is in fair to good condition. The boilers have exceeded their recommended useful life and may remain serviceable with an effective overhaul. | Replace Boiler #4 and associated controls, valves, etc. | IV | CR | 3 | 4 | 4 | 5 | 16 | Medium | 30 | 9 | 1,358 | MBH | \$110 | | | | | | | | | | \$149,380 | | | | \$149,380 |
| 6 | Boiler #5 at the north end of the vocational wing is in good to fair condition with no major deficiencies noted. Boilers #1 and #2 serving the cafeteria and north corner of the building are in good condition with no major deficiencies noted. The boilers should be overhauled to extend the service life. This should include replacement of burners and controls along with other as needed maintenance items. | Overhaul Boiler #1, #2, & #5 in the Vocational Wing | III | SM | 3 | 4 | 4 | 5 | 16 | Medium | 10 | 3 | 7,219 | MBH | \$35 | | | | | \$252,665 | | | | | | | | | \$252,665 |
| 7 | Two 10-ton split systems serving areas in the Media Center and at the New Gym were in poor condition and not operating at the time of the Site visit. | Replace 10-ton split system units at the Media Center and New Gym. | III | DM | 4 | 2 | 3 | 4 | 13 | High | 15 | 1 | 20 | TON | \$4,200 | | | | | | | | | | | | | | \$84,000 |
| 8 | Mechanical heating and cooling systems in the building utilize various pumps packages with motors ranging from 3-30-hp. Pumps should be replaced before they fail, and costs have been included as two occurrences within the study period. | Replace heating hot water pump packages and valve assemblies. | III | CR | 3 | 3 | 4 | 4 | 14 | Medium | 20 | 4 | 8 | EA | \$15,000 | | | | | \$120,000 | | | | | | | | | \$120,000 |



AXIOS
BUILDING VALUE

| Item No. | Condition | Recommendation | Priority Category | Deficiency Category | Impact of Failure | Condition of Failure | Probability of Failure | Frequency of Failure | Risk Score | Risk Category | Estimated Life | Remaining Useful Life | Quantity | Unit of Measure | Unit Cost | Year | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | Required |
|--------------------------------------|--|--|--------------------------------|---------------------|-------------------|--------------------------------|------------------------|----------------------|-------------|---------------|----------------|-----------------------|-------------|-----------------|-----------|-----------|--------------|------|------|------|------|------|----------|
| <p>Fire & Life Safety</p> | | | | | | | | | | | | | | | | | | | | | | | |
| 1 | The building is monitored by a Notifier NFS2-3030 alarm panel. At the time of the site visit, a trouble notification was noted which should be investigated and repaired. The system is approximately 15 years old and its service life due to obsolescence. It is recommended to budget for the replacement of the fire alarm control panel. | Replaces fire alarm control panel and as needed devices. | IV | CR | 3 | 4 | 5 | 5 | 17 | Low | 15 | 8 | 1 | EA | \$75,000 | | | | | | | | \$75,000 |
| 2 | Existing drawings detailing to which codes this panel was assigned in accordance with were not available for review. The school is not provided with a fire-sprinkler system. Buildings of this size typically are required to either have a sprinkler system or an approved rated assembly to protect structural elements. It is recommended to complete a more detailed fire and life safety assessment to review the code enforced at construction and the last renovation along with any details on how these ratings were achieved. | Complete life safety and code evaluation. | III | CI | 3 | 3 | 4 | 4 | 14 | Medium | 1 | 1 | 1 | EA | \$15,000 | | | | | | | | \$15,000 |
| <p>Conveyance Systems</p> | | | | | | | | | | | | | | | | | | | | | | | |
| 1 | No conveyance systems installed at the building. | | | | | | | | | | | | | | | | | | | | | | \$0 |
| <p>Summary</p> | | | | | | | | | | | | | | | | | | | | | | | |
| Deficiency | Definition | Priority | Resolution | Risk | Definition | Requirement (Total for School) | \$7,503,385 | \$5,187,773 | \$4,400,515 | \$3,170,500 | \$3,975,880 | \$2,942,000 | \$1,042,400 | \$709,000 | \$149,380 | \$816,000 | \$29,896,833 | | | | | | |
| SHA | Scheduled Maintenance | I | Currently Critical | Critical | Critical (4-8) | | | | | | | | | | | | | | | | | | |
| DMA | Deferred Maintenance | II | Potentially Critical | High | High (9-13) | | | | | | | | | | | | | | | | | | |
| CK | Capital Renewal | III | Necessary / Not yet Critical | Medium | Medium (14-16) | | | | | | | | | | | | | | | | | | |
| EM | Energy & Sustainability | IV | Permitted | Low | Low (17-20) | | | | | | | | | | | | | | | | | | |
| CI | Capital Improvement | V | Does Not Meet Code / Standards | Low | Low (17-20) | | | | | | | | | | | | | | | | | | |
| Requirement (Total for School) | | | | | | | | | | | | | | | | | | | | | | | |
| Requirement (Total for 10 Year Term) | | | | | | | | | | | | | | | | | | | | | | | |
| Requirement (Total for 15 Year Term) | | | | | | | | | | | | | | | | | | | | | | | |
| Requirement (Total for 20 Year Term) | | | | | | | | | | | | | | | | | | | | | | | |

Building: Brevard High School
GPS: 27.995, -81.691, plus machine age additions
Address: 650 W. County Club Rd
 Brevard, FL 32712



| Priority | Resolution | Risk | Definition |
|----------|--------------------------------|----------|----------------|
| I | Currently Critical | Critical | Critical (4-8) |
| II | Potentially Critical | High | High (9-13) |
| III | Necessary / Not yet Critical | Medium | Medium (14-16) |
| IV | Permitted | Low | Low (17-20) |
| V | Appearance | | |
| VI | Does Not Meet Code / Standards | | |



| Deficiency | Definition |
|------------|-------------------------|
| SHA | Scheduled Maintenance |
| DMA | Deferred Maintenance |
| CK | Capital Renewal |
| EM | Energy & Sustainability |
| CI | Capital Improvement |



Building: Breward High School
Address: 547096
 1959 (64 years), plus varying age additions
 609 N Country Club Rd
 Breward, NC 28712

Financial Summary


Facility Condition Index




10 Year Facility Condition Index

Summary by System


Expenditures by Deficiency Category



Expenditures by Risk



Expenditures by Priority Category



| FCI Range | Condition Description |
|-------------|---|
| 0.00 - 0.02 | Excellent condition, typically new construction |
| 0.02 - 0.05 | Good Condition, renovations occur on schedule |
| 0.05 - 0.1 | Fair Condition, in need of normal renovation |
| 0.1 - 0.2 | Below average condition, major renovations required |
| 0.2 - 0.5 | Poor condition, total renovation needed |
| 0.5 - 1 | Complete facility replacement indicated |

| Risk | Definition |
|----------|----------------|
| Critical | Critical (4-8) |
| High | High (9-13) |
| Medium | Medium (14-16) |
| Low | Low (17-20) |


| Priority | Definition |
|----------|---------------------------------|
| I | Currently Critical |
| II | Potentially Critical |
| III | Necessary / Not yet Critical |
| IV | Recommended |
| V | Appearance |
| VI | Does Not Meet Codes / Standards |

Building: Brevard High School
GPI: 147095
Age: 1959 (64 years), plus varying age additions.
Address: 609 N Country Club Rd
Brevard, NC 28712

Representative Photos



Area of water ingress at Auditorium



Deteriorated paint finishes at glulam beams at Old Gym



Paid mounted chiller



Original standing seam metal roofs



Failed and missing roof deck at Old Gym




Older electrical equipment



Poor drainage detailing and area of persistent water ingress




Fogged glazing at Cafeteria roof



Domestic water heaters



Roof covering at EC Wing in poor condition



Sealant joints in brickwork in poor condition



Fire alarm control panel



December 5, 2023

Transylvania County
 155 Public Safety Way
 Brevard, NC 28712
 Attn: David McNeill, Assistant County Manager

Subject: Mold Assessment
 Brevard High School
 Brevard, NC
 Project Number: FDG231120

Mr. McNeill:

At your request, Fleetwood Daniels Group, LLC (FDG) performed an indoor air quality assessment at the above referenced project location on November 27, 2023. The assessment included collection of mold spore trap air samples throughout the school buildings. Sampling was conducted under the recommendations of FDG and was under the direction of the client representative. Additionally, FDG collected two exterior air samples to be averaged and used for comparative analysis. The sample locations are identified on the attached drawing.

Sampling was requested in order to assess the general conditions of the building as it relates to mold. The air sampling was performed by Mrs. Suzanne Hinson and Mr. Clay Hinson, Industrial Hygienists with FDG.

Results - Sampling & Analysis

AIRBORNE MOLD SAMPLES

| SAMPLE NUMBER | LOCATON | LABORATORY RESULTS Total Mold |
|---------------|--|---|
| BH-1 | Exterior #1 | 6430 count/m ³ (5800 count/m ³ - Average Exterior) |
| BH-2 | Interior - Corridor at Front Office/Auditorium | 3060 count/m ³ |
| BH-3 | Interior - Front Offices | 3920 count/m ³ |
| BH-4 | Interior - Back of Auditorium | 862 count/m ³ |
| BH-5 | Interior - Auditorium Stage Area | 1180 count/m ³ |
| BH-6 | Interior - Corridor Along Side of Auditorium | 5640 count/m ³ |
| BH-7 | Interior - Band Room | 4780 count/m ³ |
| BH-8 | Interior - Classroom 802 | 627 count/m ³ |
| BH-9 | Interior - Corridor at 604 | 1960 count/m ³ |
| BH-10 | Interior - Corridor at 602 | 1490 count/m ³ |
| BH-11 | Interior - Corridor at 501 | 1570 count/m ³ |
| BH-12 | Interior - Corridor at 512 | 313 count/m ³ |

Count/m³ = spore count per cubic meter of air

AIRBORNE MOLD SAMPLES

| SAMPLE NUMBER | LOCATON | LABORATORY RESULTS Total Mold |
|---------------|--|---|
| BH-13 | Interior – Corridor Between 500 and 700 | 6430 count/m ³ |
| BH-14 | Interior – Classroom 514 | 1720 count/m ³ |
| BH-15 | Interior – Room 704 | 1180 count/m ³ |
| BH-16 | Interior – Classroom 708 | 3760 count/m ³ |
| BH-17 | Interior – Corridor at 700 Conference Rm | 1330 count/m ³ |
| BH-18 | Interior – Corridor at 711 | 2900 count/m ³ |
| BH-19 | Interior – Corridor at 403/408 | 862 count/m ³ |
| BH-20 | Interior – Corridor at 718 | 1880 count/m ³ |
| BH-21 | Interior – Corridor at 402 | 5090 count/m ³ |
| BH-22 | Interior – Corridor Outside Media Center | 2270 count/m ³ |
| BH-23 | Interior – Media Center | 235 count/m ³ |
| BH-24 | Interior – Corridor at 302 | 549 count/m ³ |
| BH-25 | Interior – Corridor at 103 | 627 count/m ³ |
| BH-26 | Interior – Corridor at Cafeteria | 5330 count/m ³ |
| BH-27 | Interior - Cafeteria | 24,100 count/m ³ |
| BH-28 | Interior - Kitchen | 11,600 count/m ³ |
| BH-29 | Interior – Lobby Between New and Old Gym | 2190 count/m ³ |
| BH-30 | Interior – Old Gym | 392 count/m ³ |
| BH-31 | Interior – Athletic Trainer Room | 2190 count/m ³ |
| BH-32 | Exterior #2 | 5170 count/m ³ (5800 count/m ³ - Average Exterior) |

Count/m³ = spore count per cubic meter of air

Conclusions

The analysis of the air samples collected show total spore counts on the interior samples collected were lower than those on the exterior of the building (average of two samples) with the exception of the samples collected in the Corridor Between 500/700, Cafeteria and Kitchen.

Analysis shows that the spore types were generally consistent with those found on the exterior of the building. Common plant molds were present on the interior samples collected throughout the building. These common exterior genera of molds and are typically found in soils and decaying plant matter, but can also grow indoors given the right conditions. Given the right conditions, indoor growth can be widespread on damp substrates as some will grow indoors at low temperatures.

Sample analysis indicates counts of *Aspergillus/Penicillium-like* spores on the samples collected from the interior of the school that were not identified on the exterior sample. *Aspergillus/Penicillium-like* spores are typically indicators of water damaged building materials and are not commonly found naturally outside. These types of mold have been shown to have the possibility of causing respiratory issues especially in people with allergies or immune deficiencies when found in indoor areas. These spores were identified on the samples collected in the Front Office Area, Corridor at 501, Corridor Between 500/700 and the Cafeteria. These spores could

be from a current water loss, or from a previous water loss in these areas. FDG would recommend further investigation in the Front Office and Cafeteria as the counts of *Aspergillus/Penicillium-like* spores were higher in these areas. FDG did not observe mold growth in the Front Office area, but did see evidence of water loss on Thermal System Insulation in the Cafeteria and the client indicated that wood beams in the area had been repaired due to areas of deterioration in the past. These could be sources of the *Aspergillus/Penicillium-like* spores. Additionally, FDG observed mold growth around the vent in the Kitchen area. A sample of the growth indicated that it was *Cladosporium* (Loaded, >300 spores), which is a common exterior spore that can also be found growing indoors, even in lower temperature areas. The surface sample also contained smaller counts of other common mold spores. FDG recommends correction of the condensation around the vent and HEPA cleaning of the surface growth.

In general, all areas of potential moisture intrusion should be addressed and corrected prior to remediation efforts where recommended. All areas should have HVAC units that provide an indoor environment with temperature and humidity levels in accordance with ASHRAE (American Society of Heating, Refrigerating, and Air-Conditioning Engineers) Standards. In the future all areas with visibly water damaged materials should be remediated as discovered to prevent an air quality concern in the future. Ways to reduce spore counts include, but are not limited to, HEPA air filtration, HEPA vacuum cleaning and/or surface cleaning with anti-microbial serum.

Observations, findings, results, and conclusions are limited to those conditions apparent at the time of the site visit. It should not be construed that actions taken as a result of this work will achieve complete compliance with every regulatory standard nor prevent every possible accident or loss. Neither should it be considered that any recommendations noted are the only possible actions to be taken.

QUALIFICATIONS

This report summarizes FDG's evaluation of the conditions observed at the subject building during the course of the survey. Our findings are based upon our observations at the building and analyses of the samples obtained at the time of this survey. Asbestos-containing materials may exist in the building, if materials are to be disturbed they should be tested for the presence of asbestos prior to disturbing. Any conditions discovered which deviate from the data contained in this report should be presented for our evaluation.

Attached with this report you will find the laboratory analytical results for each sample collected will be attached.

Fleetwood Daniels Group, L.L.C. is pleased to have provided our professional services for this project. If you have any questions or comments, please do not hesitate to call at (828) 400-1509.

Sincerely,
FLEETWOOD DANIELS GROUP, L.L.C.



Suzanne Hinson
Principal

Attachments: Laboratory Analytical Reports

Laboratory Analytical Reports



Direct Exam: Spore Trap Analysis

SAI Method B-SOP-003



Customer: Fleetwood Daniels Group
PO Box 1144
Waynesville, NC 28786

Attn: Suzanne Hinson

Lab Order ID: 10037914

Analysis: STA

Date Received: 11/28/2023

Date Reported: 11/28/2023

Project: FDG231120 - Brevard High

| Sample ID | BH-1 | BH-2 | BH-3 | EXTERIOR | | | | | |
|---|---------------|--|----------------------|---------------|--|---------------|---------------|--|---------------|
| Lab Sample ID | 10037914_0001 | 10037914_0002 | 10037914_0003 | AVERAGE | | | | | |
| Description | Exterior | Interior-corridor @ off. | Interior-office area | N/A | | | | | |
| Lab Notes | | | | N/A | | | | | |
| Volume (L) | 75 | 75 | 75 | N/A | | | | | |
| Analytical Sensitivity (counts/m ³) | 78 | 78 | 78 | N/A | | | | | |
| IDENTIFICATION | Raw Count | Concentration (counts/m ³) | % Of Total | Raw Count | Concentration (counts/m ³) | % Of Total | Raw Count | Concentration (counts/m ³) | % Of Total |
| <i>Alternaria</i> | 40 | 3130 | 48.8% | 5 | 392 | 10.0% | <1 | 39.2 | N/A |
| Ascospores | | | | 12 | 940 | 30.8% | 36 | 2780 | 48.0% |
| <i>Aspergillus/Penicillium-like</i> | | | | 31 | 2430 | 62.0% | | | |
| Basidiospores | 21 | 1650 | 25.6% | 11 | 862 | 28.2% | 21 | 1610 | 28.0% |
| <i>Cercospora-like</i> | | | | | | | | | |
| <i>Chaetomium</i> | | | | | | | | | |
| <i>Cladosporium</i> | 14 | 1100 | 17.1% | 4 | 313 | 10.3% | 13 | 981 | 17.3% |
| <i>Curvularia</i> | | | | | | | | | |
| <i>Drechslera/Bipolaris</i> | | | | | | | | | |
| <i>Epicoccum</i> | 2 | 157 | 2.44% | 3 | 235 | 7.69% | 2 | 118 | 2.67% |
| Myxomycete/Rust/Smut-like | 4 | 313 | 4.88% | 9 | 705 | 23.1% | 3 | 196 | 4.00% |
| <i>Nigrospora</i> | | | | | | | <1 | 39.2 | N/A |
| <i>Pitheomyces</i> | | | | | | | | | |
| <i>Sphaeriopsis</i> | | | | | | | | | |
| Unknown/Other | 1 | 78.4 | 1.22% | | | | <1 | 39.2 | N/A |
| TOTAL | 82 | 6430 | 100.0% | 39 | 3060 | 100.0% | 50 | 3920 | 100.0% |
| Non-Cellulosic Fibers | - | - | - | - | - | - | - | - | - |
| Hypheal Fragments | 2 | 157 | - | 2 | 157 | - | 3 | 235 | - |
| Insect Parts | - | - | - | - | - | - | - | - | - |
| Pollen | - | - | - | - | - | - | - | - | - |
| Skin Cell % of Total Debris | 0-20% | 40-60% | 60-80% | 20-40% | 60-80% | 40-60% | 20-40% | 40-60% | N/A |
| Total Debris in Background | 40-60% | 60-80% | 40-60% | 40-60% | 60-80% | 40-60% | 40-60% | 40-60% | N/A |

Disclaimer: This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. Unless otherwise noted blank sample correction was not performed on analytical results. Scientific Analytical Institute participates in the AIHA EMPAT program for fungi. EMPAT Laboratory ID: 173190. Reporting Limit equals Analytical Sensitivity. Unless indicated, areas and volumes were provided by the customer.

Darrin Parrick (32)
Analyst

[Signature]
Approved Signatory



Direct Exam: Spore Trap Analysis

SAI Method B-SOP-003



Customer: Fleetwood Daniels Group
PO Box 1144
Waynesville, NC 28786

Project: FDG231120 - Brevard High

Attn: Suzanne Hinson

Lab Order ID: 10037914

Analysis: STA

Date Received: 11/28/2023

Date Reported: 11/28/2023

| Sample ID | BH-16 | BH-17 | BH-18 | EXTERIOR | | | | | |
|---|------------------------|--|-------------------------|-----------|--|---------------|-----------|--|---------------|
| Lab Sample ID | 10037914_0016 | 10037914_0017 | 10037914_0018 | AVERAGE | | | | | |
| Description | Interior-classroom 708 | Interior-corridor @ 700 conf. | Interior-corridor @ 711 | N/A | | | | | |
| Lab Notes | | | | N/A | | | | | |
| Volume (L) | 75 | 75 | 75 | N/A | | | | | |
| Analytical Sensitivity (counts/m ³) | 78 | 78 | 78 | N/A | | | | | |
| IDENTIFICATION | Raw Count | Concentration (counts/m ³) | % Of Total | Raw Count | Concentration (counts/m ³) | % Of Total | Raw Count | Concentration (counts/m ³) | % Of Total |
| <i>Alternaria</i> | 1 | 78.4 | 2.08% | 9 | 705 | 24.3% | <1 | 39.2 | N/A |
| <i>Ascosporas</i> | 7 | 549 | 14.6% | 4 | 313 | 23.5% | 36 | 2780 | 48.0% |
| <i>Aspergillus/Penicillium-like</i> | 4 | 313 | 8.33% | 4 | 313 | 23.5% | 21 | 1610 | 28.0% |
| <i>Basidiospores</i> | | | | | | | | | |
| <i>Cercospora-like</i> | | | | | | | | | |
| <i>Chaetomium</i> | | | | | | | | | |
| <i>Cladosporium</i> | 3 | 235 | 6.25% | 2 | 157 | 11.8% | 13 | 981 | 17.3% |
| <i>Curvularia</i> | | | | | | | | | |
| <i>Drechslera/Bipolaris</i> | | | | | | | | | |
| <i>Epicoccum</i> | 6 | 470 | 12.5% | 1 | 78.4 | 2.7% | 2 | 118 | 2.67% |
| <i>Mycosporaceae/Rust/Smut-like</i> | 24 | 1880 | 50.0% | 6 | 470 | 35.3% | 3 | 196 | 4.00% |
| <i>Nigrospora</i> | | | | | | | | | |
| <i>Pithomyces</i> | 2 | 157 | 4.17% | | | | <1 | 39.2 | N/A |
| <i>Sphaerularia</i> | 1 | 78.4 | 2.08% | | | | <1 | 39.2 | N/A |
| Unknown/Other | | | | | | | | | |
| TOTAL | 48 | 3760 | 100.0% | 17 | 1330 | 100.0% | 37 | 2900 | 100.0% |
| Non-Cellulosic Fibers | - | - | - | - | - | - | - | - | - |
| Hypheal Fragments | 6 | 470 | - | 4 | 313 | - | 3 | 235 | 117.7 |
| Insect Parts | - | - | - | - | - | - | - | - | - |
| Pollen | 1 | 78.4 | - | - | - | - | - | - | - |
| Skin Cell % of Total Debris | | 40-60% | | | 40-60% | | | 40-60% | |
| Total Debris in Background | | 60-80% | | | 60-80% | | | 60-80% | |

Disclaimer: This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. Unless otherwise noted blank sample correction was not performed on analytical results. Scientific Analytical Institute participates in the AIHA EMPAT program for fungi. EMPAT Laboratory ID: 173190. Reporting Limit equals Analytical Sensitivity. Unless indicated, areas and volumes were provided by the customer.

Darrin Parrick (32)
Analyst

[Signature]
Approved Signatory



Direct Exam: Spore Trap Analysis

SAI Method B-SOP-003



Customer: Fleetwood Daniels Group
 PO Box 1144
 Waynesville, NC 28786

Attn: Suzanne Hinson

Lab Order ID: 10037914

Analysis: STA
Date Received: 11/28/2023
Date Reported: 11/28/2023

Project: FDG231120 - Brevard High

| Sample ID | BH-22 | BH-23 | BH-24 | EXTERIOR | | | | | |
|---|---------------------------------|--|-------------------------|-----------|--|------------|-----------|--|------------|
| Lab Sample ID | 10037914_0022 | 10037914_0023 | 10037914_0024 | AVERAGE | | | | | |
| Description | Interior-corridor outside media | Interior-media center | Interior-corridor @ 302 | N/A | | | | | |
| Lab Notes | | | | N/A | | | | | |
| Volume (L) | 75 | 75 | 75 | N/A | | | | | |
| Analytical Sensitivity (counts/m ³) | 78 | 78 | 78 | N/A | | | | | |
| IDENTIFICATION | Raw Count | Concentration (counts/m ³) | % Of Total | Raw Count | Concentration (counts/m ³) | % Of Total | Raw Count | Concentration (counts/m ³) | % Of Total |
| <i>Alternaria</i> | 5 | 392 | 17.2% | 1 | 78.4 | 14.3% | <1 | 39.2 | N/A |
| <i>Ascosporas</i> | 5 | 392 | 17.2% | 1 | 78.4 | 17.2% | 2 | 2780 | 48.0% |
| <i>Aspergillus/Penicillium-like</i> | | | | | | | | | |
| <i>Basidiospores</i> | | | | | | | | | |
| <i>Cercospora-like</i> | | | | | | | | | |
| <i>Chaetomium</i> | | | | | | | | | |
| <i>Cladosporium</i> | 7 | 549 | 24.1% | | | | 13 | 981 | 17.3% |
| <i>Curvularia</i> | | | | | | | | | |
| <i>Drechslera/Bipolaris</i> | | | | | | | | | |
| <i>Epicoccum</i> | 2 | 157 | 6.9% | | | | 2 | 118 | 2.67% |
| <i>Myxomycete/Rust/Smut-like</i> | 9 | 705 | 31.0% | 1 | 78.4 | 33.3% | 3 | 196 | 4.00% |
| <i>Nigrospora</i> | 1 | 78.4 | 3.45% | | | | <1 | 39.2 | N/A |
| <i>Pitheomyces</i> | | | | | | | | | |
| <i>Spegazzinia</i> | | | | | | | | | |
| Unknown/Other | | | | | | | <1 | 39.2 | N/A |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| TOTAL | 29 | 2270 | 100.0% | 3 | 235 | 100.0% | 7 | 549 | 100.0% |
| Non-Cellulosic Fibers | - | - | - | - | - | - | - | - | - |
| Hypheal Fragments | 3 | 235 | - | - | - | - | 1 | 78.4 | 117.7 |
| Insect Parts | - | - | - | - | - | - | - | - | - |
| Pollen | - | - | - | - | - | - | - | - | - |
| Skin Cell % of Total Debris | | 20-40% | - | | 0-20% | - | | 0-20% | N/A |
| Total Debris in Background | | 60-80% | - | | 20-40% | - | | 40-60% | N/A |

Disclaimer: This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. Unless otherwise noted blank sample correction was not performed on analytical results. Scientific Analytical Institute participates in the AIHA EMPAT program for fungi. EMPAT Laboratory ID: 173190. Reporting Limit equals Analytical Sensitivity. Unless indicated, areas and volumes were provided by the customer.

Darrin Patrick (32)
 Analyst

[Signature]
 Approved Signatory



MEDLOCK & ASSOCIATES ENGINEERING, PA

April 10, 2024

Mr. David McNeil, Emergency Services Director
Transylvania County
101 South Broad Street
Brevard, NC 28712

Subject: **Additional repair recommendations for Cafeteria and Gymnasium roof glulams
Brevard High School - 609 N Country Club Rd, Brevard, NC 28712**
Project Number: 758221

Dear Mr. McNeil:

As requested, a Medlock & Associates Engineering, PA (MAE) representative met with an Arborist (Bill Hascher) on Thursday, December 21, 2023, at Brevard High School (609 N Country Club Rd) to conduct testing on the glulam ends adjacent to the baseplates for each glulam. Prior repairs had been provided to ensure the proper transfer of forces from the glulams to the typical bearing base (steel base "boot" with concrete buttress and footing). These repairs were completed in October and November of 2021 for the gymnasium and cafeteria, respectively.

We discovered in late 2023 that the steel flashing shown in our construction documents were not installed during repairs. At the time of this discovery, we discussed additional observations with the county to ensure the continuing structural capacity for the gymnasium and cafeteria glulams. Each system consists of glulams penetrating the exterior walls of the gymnasium and cafeteria. After issuance of our follow up report dated January 23, 2024, we have completed the recommended repairs to extend the lifetime of the structure. After completion of the proposed repairs, it is our opinion that the repairs shall be observed and assessed every three years during occupancy of the structures.

MAE's assessment is based on visual observations and testing of structural properties of the glulams in their existing condition concluded that the attachment of glulams to bases are structurally sound. Please see our following comments and recommendations below:

1. We visually observed the glulams with the worst physical conditions for testing.
2. We evaluated five (5) glulam locations of the cafeteria along the "southeast" of the cafeteria. The glulam ends along the "northwest" side of the cafeteria were enclosed in interior space years ago and do not display any damage as the exterior exposed glulams have.
3. We evaluated three glulams along the northeast side of the gymnasium and along the southwest side of the gymnasium (6 total glulam tests – 3 each side).
4. The wood strength tests were conducted with a IML North American RESI F-400 series resistance drill. These types of drills are typical utilized to test wooden bridge beams for strength characteristics.


5. The typical testing location was approximately 16" above the top of the steel boot brackets. The testing holes were typically drilled perpendicularly to the top of each glulam at an angle to allow the testing locations between the lowest set of bolts and the adjacent row of bolts above. These tests were performed in this approximate location as the worst deterioration and rot in the glulams was nearest the steel boot brackets. Each test was performed by the arborist and observed and recorded by the Engineer of Record while on site.
6. **Based on the testing information and torque readings recorded by the resistance drill, it is our opinion that the glulam attachments at the typical steel base are stable and substantial to support the required 20 PSF roof live load. To prolong the useful life of the two structures, we recommend that the following recommendations shall be implemented (items 7, 8 and 9 below).**
7. The majority of rot damage observed in the curved glulam beam was typically observed in or near the original steel boots. The rotted wood shall be removed by hand tools to remove damaged and soft wood material. The voids and holes in the wood from the removal of rotted wood shall be filled with *Restore-Rite Non-Sag, High Strength Epoxy Wood Filler* (see the attached cut sheet for preparation and installation of the epoxy material. Alternative products may be submitted to replace the Restore-Rite epoxy based on review and approval by the engineer (MAE).
8. After the areas of rotted wood are addressed with the epoxy, we recommend installation of *Trex Self-Adhering Sheet Flashing* along the exposed top of each glulam that is exposed to the elements. The self-adhering tape shall be wrapped over the top of each glulam a minimum of 1" along each side (see detail sheet BD-1 for installation).
9. In addition to the treatment of rotted wood and installation of the top flashing, we recommend that a minimum 3/8" hole shall be drilled at the low point of each existing boot in accordance with the attached details 4 and 5 on sheet BD-1.
10. The primary purpose of addressing the rotted wood with epoxy and the installation of the flashing tape is to prolong the useful life of the two structures (cafeteria and gymnasium). The existing connection at the boot at each glulam location is currently sound with the installation of newer plates in 2021, but the rot shall be addressed to limit any future deterioration and the application of the proposed flashing is to redirect water from the top of each glulam and from the existing steel boots. As such, the flashing shall be extended a minimum of 2" over the steel boot.
11. **After all work has been completed, contact engineer for assessment and approval of the performed work. We highly recommend having an on-site meeting with a representative of the owner, the proposed contractor, and engineer prior to proceeding with the work to review and ensure that all rotted material near the glulam boots is rotted.**
12. **Due to the age and condition of the glulams for the cafeteria and gymnasium, we recommend a rough estimate of five (5) years of additional service once the repairs have been completed and approved. To ensure the proper performance of the life extension, we request and recommend that a visual inspection of the glulam base connections shall be confirmed by Medlock & Associates Engineering, or another professional engineer licensed in the state of North Carolina on a 2-year basis. This recommendation is based on the harsh exposure of the elements to the glulam beams and the possible abuse that can occur with occupancy. With the implementation of a recurring 2-year inspection program, the life of the structures (cafeteria and gymnasium) can be extended well beyond the 5 years quoted above. The purpose of the 2-year inspection is to ensure continuing performance of the repaired glulam beams (particularly regarding the weatherization taping / flashing).**

Please see the accompanying detail drawing (BD-1 dated 04-04-2024) and product information cut sheets for the proposed epoxy system and the proposed weatherization tape to ensure proper installation and performance of the proposed system. We further recommend that a contractor with experience shall provide the services for the rotted wood repair.

The scope of this report is limited to matters discussed herein. No opinion is offered, and none should be inferred, regarding other aspects of this structure or the structure taken as a whole. This report is based on presently known and available facts, data, and information. To the extent that additional or different facts, data, or information is developed or discovered after the issuance of this report, MAE reserves the right to amend, alter, or change the report as needed to reflect consideration of the additional or different facts, data, or information. Site observations are limited to visibly observable areas; we offer no opinion regarding structural conditions behind finishes or inaccessible areas. If signs of distress are observed or if new information is brought to our attention, invasive testing for further observations may be recommended. We are pleased to be of service. If you have any questions regarding this report or require further assistance, please call.

Sincerely,

Medlock & Associates Engineering, P.A., (Cert. #C3133):



Edward K Medlock, PE
President, Senior Engineer



TECHNICAL DATA SHEET

STRONGBOND EPOXY WOOD FILLER

NON-SAG, HIGH-STRENGTH EPOXY WOOD FILLER & REPAIR ADHESIVE

PRODUCT DESCRIPTION

STRONGBOND EPOXY WOOD FILLER is a two-component, rapid-curing, high-strength epoxy wood filler and multi-purpose repair adhesive. Its non-sag formula fills voids left by dry-rot, restoring strength and shape to damaged wood. It is moisture-insensitive and can be applied on damp surfaces. Because it is shrink-free and does not slump or sag, it is perfect for vertical and overhead repairs.

The Filler creates a high-strength, chemical bond to STRONGBOND EPOXY WOOD SEALER, making repairs to dry-rotted wood last longer. It can be used as a fairing compound to fill air bubbles and voids that may occur during the sanding process, then the repaired wood can be carved or machined to recreate the desired shape before applying a topcoat.

This product also is an excellent multi-purpose adhesive. It will bond to most surfaces, such as brick, ceramic tile, concrete, fiberglass, or stone.

USES

- Epoxy resin bonding for dry-rot repair. Fills voids left by dry-rot, nail holes, or missing wood
- Can be used as a fairing compound
- Cured filled surfaces may be carved or machined to restore the shape of the damaged wood
- Ideal for repairing wooden window frames and sills, rafter tails, exposed beams, decks, doors, floors, fences, boat hulls, and other wooden structural and decorative elements. The restored wood can be primed and painted with water-based paint or other epoxy-compatible topcoat
- As a multi-purpose adhesive, it creates a high-strength bond to most surfaces, such as stone, concrete, ceramic tile, and fiberglass
- Intended to be used outdoors or in well-ventilated indoor areas, in temperatures between 40 °F (4 °C) and 110 °F (43 °C)

FEATURES / ADVANTAGES

- Rapid initial 3-hour cure time at room temperature
- Non-sag, no-shrink formula makes it excellent for vertical and overhead applications
- Low VOC, low odor, and solvent-free



STRONGBOND EPOXY WOOD FILLER

- Creates a high-strength, chemical bond to STRONGBOND EPOXY WOOD SEALER. Once the sealer is tacky, apply Filler over uncured sealer and the two will cure together, saving time to complete projects
- Moisture-insensitive; can be applied on damp surfaces and underwater
- Easy-dispensing with coaxial cartridges, which are packaged with a nozzle that automatically mixes the product in the precise ratio. Cartridges fit into standard 10 oz. caulking guns for flow-control installation

PRODUCT INFORMATION

| | |
|-------------------------|---|
| Availability | Restore-Rite™ products are available through select distributors. |
| Available Sizes | <p>Coaxial Cartridge – 8.6 oz. (256 ml) Includes one mixing nozzle that automatically mixes precise ratio of Parts A and B. (Cartridges fit into standard 10 oz. caulking guns.)</p> <p>Bulk-Packaging – Quart Kit Kit contains 16 oz. (473 ml) Part A and 16 oz. (473 ml) Part B for 1:1 mixing ratio</p> <p>Bulk-Packaging – 102 oz. Kit Kit contains 51 oz. (1.5L) Part A and 51 oz. (1.5L) Part B for 1:1 mixing ratio</p> |
| Application Temperature | 40°F and 110°F (4°C and 43°C) |
| Color | Part A (Resin) White; Part B (Hardener) Dark Gray; Mixed: Gray |
| Cure Time | 3 hours at 75°F initial cure; fully cured in 24 hours |
| Mix Ratio | 1:1 by volume (refer to MPII in this TDS) |
| Gel Time | 26 minutes at 75°F (based on 60 gram mass) |
| Shelf Life | 24 months in unopened containers stored in dry and dark conditions. |
| Storage | Between 40°F (4°C) and 95°F (52°C). Store in closed containers, in a secure, dry place not exposed to direct sunlight or extremely low or high temperatures |
| VOC Content | 17 g/L (mixed) |
| Working Time | 45 minutes at 75°F (nozzle) |



STRONGBOND EPOXY WOOD FILLER

LIMITATIONS & WARNINGS

- Cartridge balancing and other installation instructions must be strictly followed. (Refer to MPII)
- Do not thin with solvents, as this will prevent cure.
- Before applying Filler over STRONGBOND EPOXY WOOD SEALER, the sealer must first become tacky.
- Product will cure slower in thinner film and/or colder temperatures and faster in a larger mass and/or elevated temperatures.
- Best when applied in increments at a thickness of 1 inch or less. A larger mass will generate excessive heat. For filling larger voids, a dry piece of scrap wood treated with STRONGBOND EPOXY WOOD SEALER can be used as a filler block, and attach it inside the void with wood screws. This process will allow a smaller mass of Filler to be used.
- May discolor from UV exposure. Filler should cure at least 3 hours prior to sanding and coating with water-based paint or other epoxy-compatible topcoat to meet the desired appearance. Use of solvent-based coatings should be avoided. Coating in a small test area is recommended prior to completing the entire project.
- Product is not intended for repairing weight-bearing structural elements. Consult an architect.
- NEVER leave mixed epoxy in an unattended open container as its thermolytic process generates heat and it will eventually heat-up and produce smoke.
- When dispensing underwater, product may sag.

Clean Up: Always wear appropriate protective equipment such as chemical-resistant nitrile rubber gloves and splash-proof safety chemical goggles during cleanup. Clean uncured materials from tools and equipment with a mild solvent, such as mineral spirits. Cured material can only be removed mechanically. Dispose of product in accordance with federal, state and local regulations.

Safety: Always refer to the Safety Data Sheet (SDS) for both Part A and Part B at www.restore-rite.com. Be sure to wear protective chemically-resistant gloves, clothing and goggles during application and clean-up. Ensure indoor areas are properly ventilated. For more information, call New Enterprises at 1-415-722-9098. In an emergency, contact CHEM-TEL 1-800 255-3924 (24 hours).

INSTRUCTIONS

In order to achieve maximum results, **proper application is imperative**. Carefully read the Manufacturer's Printed Installation Instructions (MPII) in this TDS. Always use the most current version of the MPII, due to occasional updates and revisions.



STRONGBOND EPOXY WOOD FILLER

MANUFACTURER'S PRINTED INSTALLATION INSTRUCTIONS (MPII)

SURFACE PREPARATION


Surface preparation will depend upon the application of the product. The wood being treated must be clean of all dry-rot debris, paint, dust, oil, and wax. A clean surface free of loose material and dust is imperative for good adhesion. Always be sure the bonding surfaces are prepared and sealed with STRONGBOND EPOXY WOOD SEALER in advance before starting a new cartridge or mixing the Filler. To create a long-lasting bond, apply Filler over uncured Sealer once the sealer becomes tacky and the two will cure together. If possible, schedule dispensing to consume an entire cartridge at one time with no interruption of epoxy flow. For bulk, mix only enough product that can be used within the gel time.

CARTRIDGE PREPARATION

CAUTION: Always check the expiration date on the cartridge. **Do not use expired product!**



1. Remove the protective cap from the adhesive cartridge and insert the cartridge into the recommended dispensing tool. Before attaching the mixing nozzle, balance the cartridge by dispensing a small amount of material until both components are flowing evenly.



2. Screw on the mixing nozzle supplied with the cartridge after properly balancing the cartridge. Do not modify mixing nozzle. Confirm that the internal mixing element is in place prior to dispensing adhesive. Take note of the air and base material temperatures and review the working/full cure time prior to injection.



3. Dispense the initial amount of material from the mixing nozzle onto a disposable surface until the product is a uniform gray color with no streaks. Adhesive must be properly mixed in order to perform as published. Dispose of the initial amount of adhesive according to federal, state and local regulations.

CAUTION: When changing cartridges, **never re-use nozzles.** A new nozzle should be used with each new cartridge and Steps 1 - 3 should be repeated.

NOTE: When the work environment or substrate falls below 70°F (21°C) warm the cartridge to 70-75°F (21-24°C) prior to use. All usable material is completely dispensed when plunger reaches halfway. Schedule dispensing to consume an entire cartridge at one time with no interruption of flow to prevent material from hardening in mixing nozzle. If you have any problems in dispensing product, replace the nozzle; the product may have begun to cure in the nozzle which will affect the mix ratio. **NEVER transfer a used nozzle to a new cartridge and DO NOT attempt to force adhesive out of a hardened nozzle.**




STRONGBOND EPOXY WOOD FILLER

Mixing Without A Nozzle: Remove the protective cap from the cartridge and insert the cartridge into the recommended dispensing tool. Begin to dispense product through the opening until both products dispense equally and discard this small amount. Dispense equal portions of Part A and Part B onto a flat surface. Mix both components together using a putty knife or similar flat tool until a consistent gray color without streaks is achieved.

BULK MIXING

Thoroughly stir Part B with a mixing paddle (i.e. Jiffy mixer or similar) before mixing Parts A and B together. Smaller batches can be mixed by hand in a graduated mixing cup with a paint stir stick, or with a putty knife on scrap cardboard. Blend until a consistent gray color without streaks is achieved.

NOTE: Cold product may become too thick. Product that is too warm will react faster than normal.



1. Before mixing Parts A and B together, thoroughly mix Part B in a clean pail with a low-speed drill (400 – 600 rpm) that has a paddle attachment.
2. Proportion equal parts by volume at an exact 1:1 mix ratio. STRONGBOND EPOXY WOOD FILLER uses 1 part by volume of component Part A and 1 part by volume of component Part B. Mix only the amount of material that can be used before the gel time expires (refer to Product Information in this TDS).
3. Mix thoroughly with a low-speed drill, carefully scraping the sides and the bottom of the container while mixing. Keep the paddle below the surface of the material to avoid entrapping air. Proper mixing will take at least 3 minutes. When well-mixed, the material will be free of streaks or lumps.
4. Smaller batches may be mixed by hand in a graduated mixing cup with a paint stir stick, or with a putty knife on scrap cardboard. Blend until a consistent color without streaks or lumps is achieved.

Once the product is mixed, immediately fill voids and trowel slightly above the surface level, leaving enough material to later sand the surface down to the desired shape. After voids are filled, use a putty knife or plastic spreader to reconstruct the desired shape. For a textured finish, sawdust may be added. Once the uncured Filler no longer sticks to the sandpaper, it may be mechanically sanded. Product can be used as a fairing compound during the sanding process to fill any air bubbles or voids that may occur.

USE AS A MULTI-PURPOSE ADHESIVE

STRONGBOND EPOXY WOOD FILLER is an excellent multi-purpose adhesive. It will bond to most surfaces, such as fiberglass, ceramic tile, concrete, stone, or brick. Use an appropriate amount of material for bonding to clean and prepared surfaces.



Trex Protect™
JOIST & BEAM TAPE

2190 WEST BATES AVE.
ENGLEWOOD, COLORADO 80110
TEL + 1-720-348-1385
WWW.TREXPROTECT.COM
INFO@TREXRAINESCAPE.COM

SECTION 07 65 26

Self-Adhering Sheet Flashing – TREX® Protect™

TREX® Protect™ products are manufactured and sold by IBP, LLC under a Trademark License Agreement with Trex Company, Inc. Protect™ is a federally registered trademark of IBP, LLC.

TREX® Protect™ our self-adhesive, non-skid deck flashing tape. This butyl-based tape is designed to shield joists and beams from moisture that can lead to wood rot and decay.

PART 1 GENERAL

1.1 SECTION INCLUDES

- A. Construction Tapes.

1.2 REFERENCES

- A. ASTM International:
 1. ASTM D 1970/ D 1970 M - 20: Standard Specification for Self-Adhering Polymer Modified Bituminous Sheet Materials Used as Steep Roofing Underlayment for Ice Dam Protection
 2. ASTM D 3330/D 3330 M - 04: Standard Test Method for Peel Adhesion of Pressure-Sensitive Tape
 3. ASTM D 3767 – Standard Practice for Rubber – Measurement of Dimensions.
 4. ASTM D 5034 - 09: Standard Test Method for Breaking Strength and Elongation of Textile Fabrics.
 5. ASTM G154: Standard that is used as the basis for all other accelerated weathering standards that use fluorescent UV light sources to stimulate exposure to natural sunlight.

1.3 SUBMITTALS

- A. Submit under provisions of Section 01300.
- B. Product Data: Manufacturer's data sheets on each product to be used, including:
 1. Preparation instructions and recommendations.
 2. Storage and handling requirements and recommendations.
 3. Installation methods.

1.4 QUALITY ASSURANCE

- A. Installer Qualifications: Experienced in installation of specified material type with working knowledge of specified products and Project specific application requirements.

1.5 DELIVERY, STORAGE, AND HANDLING

- A. Material should be left in its original packaging until use.
- B. Store indoors, between 40 – 100 degrees F.
- C. Acclimate to installation temperature before use.
- D. Do not lay butyl tape on side after removed from packaging.
- E. Do not stack boxes above:
 - 1. Butyl tape 4 or fewer boxes tall
 - 2. Do not stack heavier boxes on lighter boxes
- F. Store and dispose of solvent-based materials, and materials used with solvent-based materials, in accordance with requirements of local authorities having jurisdiction

1.6 PROJECT CONDITIONS

- A. Maintain environmental conditions (temperature, humidity, and ventilation) within limits recommended by manufacturer for optimum results. Do not install products under environmental conditions outside manufacturer's recommended limits.

1.7 WARRANTY

- A. Limited Warranty:
 - 1. Manufacturer warrants materials to not de-laminate, blister, peel, or dissolve from exposure to ultraviolet rays for a period of **twenty years** from the date of purchase when applied according to published directions.
 - 2. Specific terms for warranties can be found at: <https://trexprotect.com/warranty/>

PART 2 PRODUCTS

2.1 MANUFACTURERS

- A. Contract Documents are based on products supplied by; IBP, LLC, 2190 West Bates Ave., Englewood, CO 80110
- B. Substitutions: Not permitted under Division 01

2.2 CONSTRUCTION TAPES

- A. Self-Adhering Protective Wrap:

TREX® Protect™ is a self-adhering butyl-based deck flashing tape to protect wood decks and posts from premature rot and corrosion. Installation includes horizontal and vertical surfaces including all joists, rim joist, beams, steps, stair stringers, blocking, ledger board, under joists hangers and other surface. Apply at temperatures above 50° F (10°C). The product is self-sealing around fasteners to prevent water damage. Product comes packaged in individually wrapped and labeled rolls. Product offers a 20-year warranty.

1. Product: TREX® Protect™ as manufactured by IBP, LLC.

- a. **Rim Tape: 11" wide x 50', 0035.**
- b. **Description: A self-adhering butyl-based deck flashing tape that protects the joists and beams from moisture that can lead to wood decay**
- c. **Sealing: Self-sealing around deck fasteners.**
- d. **Protective Release Liners: Removed when product is installed**
- e. **Technical Properties:**
 - 1) **Material Color: Black**
 - 2) **Material Thickness (ASTM D 3767): 20 mils (0.508mm) Nominal.**
 - 3) **Installation Temperature: Greater than 50 degrees F (10 degrees C).**

| Performance | Method | Results | |
|--|--|-----------------------------|------------|
| Tensile strength (psi) | ASTM D 5034, modified | 15 lbf/in @ 600% elongation | |
| Water penetration around nails | ASTM D 1970 section 7.9 modified 1.25" water / 24 hours | PASS | |
| Water penetration around nails after thermal cycling | ASTM D 1970 section 7.9 modified 1.25" water / 24 hours* | PASS | |
| Water penetration around screws (#10 x 3 1/2") | ASTM D 1970 section 7.9 modified 1.25" water / 24 hours | PASS | |
| Water penetration around screws (#10 x 3 1/2") after thermal cycling | ASTM D 1970 section 7.9 modified 1.25" water / 24 hours* | PASS | |
| Peel Adhesion to various substrates (lbf/in) | ASTM D 3330 Method F | OSB (APA-Smooth Side) | 4.2 |
| | | Anodized Aluminum | 2.9 |
| | | Extruded PVC | 3.1 |
| | | Plywood (APA-B/C) | 4.5 |
| Accelerated aging | (ASTM G154, cycle 1 for 336 hours) | No Change PASS | |
| *Elevated temperature exposure AAMA 711-13 Level 3 | (7days @ 176F) Thermal Cycling (10 cycles of 8 hours @120F/16 hour @ -40F) | PASS | |
| Peel adhesion after water Immersion | (7-day soak per AAMA 800 sect. 2.4.1.4.3) | PASS | |

PART 3 EXECUTION

3.1 INSTALLATION

- A. Install according to TREX® Protect™ installation guidelines.
<https://trexprotect.com/#installation>

END OF SECTION

Artifact 1

These pictures show one beam in the cafeteria building. Currently, the engineers suggest adding epoxy and enclosing it in metal. After this repair, the engineers said to inspect every two years; the life span can be five years. See Attachment E document from the engineers.



Artifact 2

These pictures represent the inside of the cafeteria. One photo shows an old two-pipe HVAC system, and the other shows a beam located within the cafeteria. Please note that the beam has already been repaired without outside weather conditions affecting its life.



Artifact 3

These pictures represent the eaves on the 1949 gym building.



Artifact 4

These pictures represent just some of the ceiling rot that has occurred from the roof leaks.



Artifact 5

These pictures represent the damage to the gym floor from the roof/ceiling leaks.



Artifact 6

One picture shows how, after a hard rain, parts of the ceiling fall onto the gym floor. The other picture shows how the beams support the building. This particular picture is of one side of the gym.



Artifact 7

These pictures represent the beams that are located on the gym.

