

REPORT OF FACILITY CONDITION ASSESSMENT



TC Henderson Elementary

Property Address:

11839 Rosman Hwy
Lake Toxaway, NC 28747

Prepared For:

Transylvania County
Board of Commissioners
101 South Broad Street
Brevard, NC 28712

Prepared By:

Axias
Project No. GA23-017
February 26, 2024



Item No.	Condition	Recommendation	Priority Category	Deficiency Category	Impact of Failure	Condition	Probability of Failure	Frequency of Failure	Risk Score	Risk Category	Estimated Useful Life	Remaining Useful Life	Quantity	Unit of Measure	Unit Cost	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	Required	
																Year	1	2	3	4	5	6	7	8	9	10	
Interiors Required																											
1	Interiors appeared to be typical finishes and fair condition for an educational establishment. Allowance for interior finishes renewal. Timing and scope will vary based on future program needs. Allowance only includes renewal of interior finishes and minor renovations of restrooms. Does not include reconfiguration of space or address items related to educational adequacy.	Allowance for renewal of interior finishes.	V	CR	5	3	5	5	18	Low	15	5	28,000	SF	\$75.00					\$2,100,000						\$2,100,000	
2	A physical security assessment was provided by Safe Havens International. As part of their assessment, they identified areas within the school which should be provided with a vestibule to limit continued access throughout the school. Based on this recommendation, it is recommended to budget for the installation of vestibules to limit access throughout the school.	Construct vestibules per Physical Security Assessment.	II	CI	3	3	3	3	12	High		2	28,000	SF	\$3.00		\$84,000									\$84,000	
Mechanical Required																											
1	Heating hot water is provided by a Peerless 1,077-MBH oil fired boiler installed in 2000. This system appeared to be in fair condition, but replacement based on age is expected.	Replace heating hot water boiler.	III	CR	4	4	4	4	16	Medium	25	5	1,077	MBH	\$110					\$118,470						\$118,470	
2	Air conditioning is provided by a combination of split system units, package units, and air handling units with chilled and hot water coils. Two of the split systems were manufactured by McQuay in 2000 with a rated capacity of 10-tons. An additional 2-ton split system was also noted on site. Based on the age of the split systems, it is recommended to budget for the replacement of the condensing units and interior fan coil units.	Replace 10-ton McQuay and 2-ton split systems.	III	CR	3	3	4	4	14	Medium	20	1	22	TON	\$3,750	\$82,500										\$82,500	
3	Air conditioning is provided by a combination of split system units, package units, and air handling units with chilled and hot water coils. One of the split systems was manufactured by International Comfort System in 1999 with a rated capacity of 5-tons. Based on the age of the split system, it is recommended to budget for the replacement of the condensing unit and interior fan coil unit.	Replace 5-ton ICS split system.	III	CR	3	3	4	4	14	Medium	20	1	5	TON	\$3,750	\$18,750										\$18,750	
4	Air conditioning is provided by a combination of split system units, package units, and air handling units with chilled and hot water coils. The package unit was manufactured by Carrier in 2013 with a rated capacity of 7.5-tons. Based on the age of the split system, it is recommended to budget for the replacement of the package unit in the late-term.	Replace 7.5-ton Carrier package unit.	IV	CR	4	4	4	5	17	Low	20	9	7.5	TON	\$35,750									\$268,125	\$268,125		



Item No.	Condition	Recommendation	Priority Category	Deficiency Category	Impact of Failure	Condition	Probability of Failure	Frequency of Failure	Risk Score	Risk Category	Estimated Useful Life	Remaining Useful Life	Quantity	Unit of Measure	Unit Cost	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	Required	
																Year	1	2	3	4	5	6	7	8	9	10	
Plumbing Required																											
1	Domestic water is provided via a well system. Pressure tanks and a water treatment system are provided in the boiler room and a water treatment system is located in the pump house. Th system appeared to be in fair to good condition with no reported issues. It is recommended to budget an allowance for as needed pump, pressure tanks, and water treatment system replacements in the mid-term.	Allowance for as needed well system replacements.	III	CR	4	4	4	5	17	Low	15	5	1	ALLOW	\$15,000					\$15,000						\$15,000	
2	Domestic hot water is provided by a electric storage tank type water heaters. Two smaller capacity water heaters were manufactured by AO Smith while the larger capacity, approximate 125-gallons, was manufactured by PVI. We anticipate that the smaller capacity water heaters will be replaced as routine maintenance, but given the cost of the PVI water heater, it is recommended to budget for its replacement.	Replace PVI water heater.	III	CR	3	4	4	5	16	Medium	15	3	1	EA	\$40,000			\$40,000								\$40,000	
3	The school has one 8,000-gallon underground storage tank which stores No. 2 fuel oil. The tank was reportedly installed in 1956 and reported to be a single wall type tank. Based on the age of the tanks it is recommended to continue to monitor the condition of the tanks through annual testing and active monitoring. An allowance for removal of the tanks has been provided; however, the timing will be driven by monitoring and testing results.	Remove underground storage tank and install new above ground code/regulation compliant storage tank.	III	CR	3	3	4	4	14	Medium	30	3	1	ALLOW	\$110,000			\$110,000								\$110,000	
Fire & Life Safety Required																											
1	A fire detection and alarm system is provided within the building. The system is NFS-320 manufactured by Notifier. The panel is reportedly still supported by the manufacturer. However, given the potential for component obsolescence, it is recommended to upgrade the fire alarm panel during the study period.	Replace/upgrade the fire alarm control panel, annunciator panel, and as needed devices.	III	CR	3	4	4	4	15	Medium	15	4	1	EA	\$25,000				\$25,000							\$25,000	
Conveyance Systems Required																											
1	The building has no conveyance systems.	N/A																								\$0	

Deficiency	Definition
SM	Scheduled Maintenance
DM	Deferred Maintenance
CR	Capital Renewal
EN	Energy & Sustainability
CI	Capital Improvement

Priority	Definition
I	Currently Critical
II	Potentially Critical
III	Necessary / Not yet Critical
IV	Recommended
V	Appearance
VI	Does Not Meet Codes / Standards

Risk	Definition
Critical	Critical (4-8)
High	High (9-13)
Medium	Medium (14-16)
Low	Low (17-20)


Required Cost (2023 US-Dollars)	\$700,410	\$288,000	\$171,200	\$25,000	\$2,596,470	\$300,000	\$0	\$0	\$268,125	\$0	\$4,349,205
Required Cost (Inflated @ 8% for 1st 3 years then 3% Per Yr.)	\$756,443	\$335,923	\$215,663	\$28,138	\$3,010,020	\$358,216	\$0	\$0	\$349,842	\$0	\$5,054,245
Total Cost (2023 \$/ SF/ Yr.)	\$25.01	\$10.29	\$6.11	\$0.89	\$92.73	\$10.71	\$0.00	\$0.00	\$9.58	\$0.00	\$155.33




Building: TC Henderson Elementary
GSF: 28000
Age: 1956 (67 years)
Address: 11839 Rosman Hwy
 Lake Toxaway, NC 28747

Financial Summary

Facility Condition Index



10 Year Facility Condition Index




FCI Range	Condition Description
0.00 – 0.02	Excellent condition, typically new construction
0.02 – 0.05	Good Condition, renovations occur on schedule
0.05 – 0.1	Fair Condition, in need of normal renovation
0.1 – 0.2	Below average condition, major renovation required
0.2 – 0.5	Poor condition, total renovation needed
0.5 – 1	Complete facility replacement indicated


Risk	Definition
Critical	Critical (4-8)
High	High (9-13)
Medium	Medium (14-16)
Low	Low (17-20)

Priority	Definition
I	Currently Critical
II	Potentially Critical
III	Necessary / Not yet Critical
IV	Recommended
V	Appearance
VI	Does Not Meet Codes / Standards


Summary by System




Expenditures by Risk




Expenditures by Deficiency Category



Expenditures by Priority Category



Representative Photos



Wooden bridge walkway towards lower play area with some deterioration.



Damaged asphalt in front of school.



Overview of pump house.




Overview of corrugated metal pitch roof and asphalt shingle roof



Exterior brick façade with aluminum framed doors and windows along with surface staining.



Exterior brick façade with aluminum framed doors and metal canopy.



Obsolete Johnson Controls HVAC controller.



Typical condition of exterior sealants.



Typical interior with vinyl tile flooring, CMU block walls and acoustical ceiling.



Peerless boiler unit.



Carrier packaged Unit.



NFS-320 fire alarm control panel (FACP).