

<i>Loc</i>	<i>Code</i>	<i>Description</i>	<i>Amount</i>	<i>Specs & Bids</i>	<i>P.O.</i>	<i>Started</i>	<i>Complete</i>
BHS	4.5120.001.529.308.000	CTE AIR HANDLERS	39,000	✓	✓	✓	✓
BHS	4.5501.001.529.308.000	GYM FLOORS	3,500	✓	✓	✓	✓
BMS	4.5501.001.529.312.000	GYM FLOORS	1,300	✓	✓	✓	✓
RHS	4.5501.001.529.328.000	GYM FLOORS	2,400	✓	✓	✓	✓
BES	4.6580.001.529.304.000	RESTROOM TILE REPLACEMENT	15,000	✓	✓	✓	✓
RES	4.6580.001.529.324.000	RESTROOM TILE REPLACEMENT	10,000	✓	✓	✓	✓
TCHES	4.6580.001.529.336.000	RESTROOM TILE REPLACEMENT	2,400	✓	✓	✓	✓
BHS	4.6580.001.532.308.000	NORTH PARKING REPAIR	128,000	✓	✓	✓	✓
BES	4.6581.001.529.304.000	1ST AND 4TH GRADE RESTROOM STALLS	13,500	✓	✓	✓	✓
BES	4.6583.001.532.304.000	PAVING REPAIRS	2,500	✓	✓	✓	✓
SYS	4.9175.334.529.328.000	CTE BUILDING ADDITION-QSCB	1,171,000	✓	✓	✓	
BHS	4.5210.001.529.308.000	ROOF REPLACEMENT-SPECIAL NEEDS	53,720	✓	✓	✓	
BHS	4.5501.001.532.308.000	FOOTBALL FIELD MAINTENANCE	3,500	NA	NA	✓	✓
RHS	4.5501.001.532.328.000	FOOTBALL FIELD MAINTENANCE	3,500	NA	NA	✓	✓
DRS	4.5850.001.529.320.000	STAIRWELL AND CAFETERIA CAMERAS	700				
SYS	4.6550.001.529.000.000	GAS PUMPS	6,000				
BMS	4.6580.001.529.312.000	PAGING SYSTEM	10,000				
DRS	4.6580.001.529.320.000	HVAC FENCING	1,750				
BHS	4.6582.001.529.308.000	BLEACHER REPAIR	4,200				
PFES	4.6581.001.532.318.000	FENCING	16,200				
RES	4.6582.001.532.324.000	FENCING	9,000				
TCHES	4.5850.001.541.336.000	VIDEO SECURITY SYSTEM	3,500				
BHS	4.6581.001.529.308.000	STADIUM INSPECTION	2,700				
DRS	4.6581.001.529.320.000	EXTERIOR DOORS	4,500				
RES	4.6581.001.529.324.000	MORE@FOUR ROOF	4,000				
RHS	4.6581.001.529.328.000	NEW GYM EXTERIOR DOORS	6,000				
SYS	4.6610.001.418.000.000	SOFTWARE PACKAGE	15,000				
PFES	4.6580.001.529.318.000	NEW FRONT ENTRY DOOR	2,500				
RHS	4.6580.001.529.328.000	OIL TANK REPAIR/REPLACEMENT	30,000				
RHS	4.6580.001.532.328.000	PAVING REPAIRS	5,000				
TCHES	4.6581.001.529.336.000	K-WING HOT WATER AND ART SINK	7,000				
BES	4.6582.001.529.304.000	CLASSROOM DOOR REPLACEMENTS	23,000				
RHS	4.6582.001.529.328.000	FIRE ALARM SYSTEM	40,000				