

<i>Loc</i>	<i>Description</i>	<i>Code</i>	<i>Amount</i>	<i>Specs &amp; Bids</i>	<i>P.O.</i>	<i>Started</i>	<i>Complete</i>
BHS	GYM FLOORS	4.5501.001.529.308.000.00	5,800	✓	✓	✓	✓
BHS	FOOTBALL FIELD REPAIR	4.5501.001.532.308.000.00	25,000	✓	✓	✓	✓
BHS	CTE AIR HANDLERS	4.5120.001.529.308.000.00	39,000	✓	✓	✓	✓
BMS	GYM FLOORS	4.5501.001.529.312.000.00	2,800	✓	✓	✓	✓
DRS	SECURITY CAMERAS	4.5850.001.529.320.000.00	11,000	✓	✓	✓	✓
RHS	GYM FLOORS	4.5501.001.529.328.000.00	5,600	✓	✓	✓	✓
RHS	ROOF REPAIR - CTE WING	4.5120.001.529.328.000.00	9,000	✓			
DRS	HVAC FENCING	4.6580.001.529.320.000.00	1,750				
RHS	OIL TANK REPAIRS AND REPLACEMENT	4.6580.001.529.328.000.00	30,000	✓	NA	✓	
SYS	GAS PUMP ROOF	4.6550.001.529.000.000.00	6,000				
BES	REPLACE CEILING TILE	4.6582.001.529.304.000.00	12,500				
BHS	ROOF REPLACEMENT - SPECIAL EDUCATION	4.5210.001.529.308.000.00	44,720	✓			
SYS	QSCB BOND PAYMENT	4.8300.334.381.000.000.00	64,924				
BES	1ST AND 4TH GRADE RESTROOM STALLS	4.6581.001.529.304.000.00	13,500				
BES	RESTROOM TILE REPLACEMENT	4.6580.001.529.304.000.00	15,000				
BHS	NORTH PARKING LOT RESURFACING AND DRAINAGE	4.6580.001.532.308.000.00	78,000				
RES	RESTROOM TILE REPLACEMENT	4.6580.001.529.324.000.00	10,000				
TCHES	RESTROOM TILE REPLACEMENT	4.6580.001.529.336.000.00	2,400				